

A

B

C

1


CS ..

1


Draft Check

100


1



-0.10
-0.20



12 x M3 20
-M3Screw-Middle...



+1
R18.75 +0.50

~~6 x M3 ✓~~ Through Hole