

(a) R_F under the package
(b) trace under the body
(c) trace around the package
1.0
0.0
−1.6
z (mm)
−2
0
2
x (mm)
y (mm)
(d)
0402 R_F
0603 R_F
$C_{F,\mathrm{par}}$ (fF)
0
20
40
60
80
56
62
72
64
53
56
R_F under the package
trace under the body
trace around the package