
LO Leakage at the "TX-side FR3 RF Out" Connector after Calibration (Cold)
Range across the other filter settings (min to max)
Median across the other filter settings
Pass level: −20 dBm (88.9% of all 1591 readings at or below it)
Fail
Pass
LO Leakage (dBm)
0
−10
−20
−30
−40
−50
−60
6
8
10
12
14
16
18
20
22
24
LO Frequency (GHz)