

## Drawing for Metal Plate Workers

By-

RareBooksClub. Paperback. Book Condition: New. This item is printed on demand. Paperback. 798 pages. Original publisher: Houston, Tex.: McDonnell Douglas Astronautics Company, Houston Division; Marshall Space Flight Center, Ala.: National Aeronautics and Space Administration, George C. Marshall Space Flight Center, 1987 OCLC Number: (OCoLC)70320574 Subject: Space shuttles. Excerpt: . . . INDEPENDENTORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET HDW FUNC DATE: I 13 87 HIGHEST CRITICALITY SUBSYSTEM: FRCS FLIGHT: 3 2R MDAC ID: 827 ABORT: 3 3 ITEM: MANIFOLD 5, OX and FU ISOL VLV SWITCH FAILURE MODE: SWITCH FAILS IN THE CLOSED POSITION SUBSYS LEAD: D. J. PAUL LEAD ANALYST: V. J. BURKEMPER BREAKDOWN HIERARCHY: ELECTRICAL COMPONENTS i) CONTROLS 2) PROP STOR and DIST SUBSYSTEM 3) 4) MANIFOLD 5, OX and FU ISOL VLVS S) MANIFOLD 5, OX and FU ISOL VLV SWITCH 6) V) 8) 9) CRITICALITIES FLIGHT PHASE HDW FUNC ABORT HDW FUNC PRELAUNCH: 3 3 RTLS: 3 3 LIFTOFF: 3 3 TAL: 3 3 ONORBIT: 3 2R AOA: 33 DEORBIT: 33 ATO: 33 LANDING SAFING: 33 REDUNDANCY SCREENS: A 2 B P C P LOCATION: PNL 08 34 PART NUMBER: 33V73A8S34...





## Reviews

An exceptional ebook along with the font applied was interesting to read through. it was actually writtern really completely and beneficial. Once you begin to read the book, it is extremely difficult to leave it before concluding.

-- Mr. Hector Cole Jr.

This written pdf is wonderful. It can be writter in easy phrases and not difficult to understand. Your lifestyle span will likely be enhance once you full looking over this ebook.

-- Juanita Reynolds