
J1/J2/J3 pins upwards J4/J5 DNP

downwards

Other pins

SDRR Rev G1



All passives 0402

3 = F405/4152 = F446

F401,

0