吴先生, 您好:

粤总 and 毓杰, 您们好:

如之前沟通,根据已收集的 dump,针对此问题,目前已分析完毕。请您<mark>邮件确认此问题分析</mark>结果:

Case No: CAS-02812-Q3D7K7

问题描述:

用户反馈, 登录华为云桌面, 输入完密码电脑蓝屏, 希望分析蓝屏原因。

问题分析:

在开启 special pool 的情况下,detect 到外设类 PNP 设备在发起 irp 之后,被华为云桌面执行 complete 的违规操作,导致蓝屏。

正常情况下,操作系统或应用程序在访问外设类 PNP 设备进行 IO 操作时,会根据设备发起的 irp 进行判断,最终传递至需要进行 IO 操作的场景。此案例中,在处理非华为云桌面客户端接收的 IO 操作时,hwusbclient 应在处理 PNP irp 事件中标注 pass down,以使得irp 继续向下层传递,然而华为云桌面错误标记为 complete,最终导致蓝屏。

具体分析如下:

2: kd>!mex.crash

Dump Info

Dump Name: MEMORY-huaweil. DMP

Windows 10 Kernel Version 17763 MP (4 procs) Free x64 Product: WinNt, suite: TerminalServer SingleUserTS

Edition build lab: 17763. 1. amd64fre. rs5 release. 180914-1434

Kernel base = 0xffffff800`3ba0e000 PsLoadedModuleList =

0xffffff800\dagger3be286f0

Debug session time: Tue Aug 18 14:39:36.730 2020 (UTC + 8:00)

System Uptime: 0 days 0:05:38.360

Processor: Intel(R) Core(TM) i5-4300U CPU @ 1.90GHz Bugcheck: C9 (22E, FFFFF8003E88AD80, FFFFA40F24CAE270, 0) Kernel Complete Dump File: Full address space is available.

Bugcheck details

DRIVER VERIFIER IOMANAGER VIOLATION (c9)

The IO manager has caught a misbehaving driver.

Arguments:

Arg1: 000000000000022e, The caller has completed a successful IRP_MJ_PNP instead of passing it down.

Arg2: fffff8003e88ad80, The address in the driver's code where the error was detected.

Arg3: ffffa40f24cae270, IRP address.

Arg4: 00000000000000000

根据 bugcheck 和 call stack, 问题是三方 IO 驱动 hwusbclient 在进行 IO 操作时引起的, 具体的说明可以参考如下的 link:

https://docs.microsoft.com/en-us/windows-hardware/drivers/debugger/bug-check-0xc9--driver-verifier-iomanager-violation

0x22E	Non-fatal error	The caller has completed a successful IRP_MJ_PNP instead of passing
		Param 2 - The address in the driver's code where the error was detect
		Param 3 - IRP address.

Crashing Stack

Process Thread C

ID UserTime KernelTime ContextSwitches Wait

Reason Time State

System (ffffa40ef2f0a440) ffffa40f25282700

4. 1e00 0s 2s. 594 74052

WrYieldExecution Os Running on CPU 2

Irp List:

IRP File Driver

ffffa40efcf23010 USBHUB3

Child-SP Return Call

Site

Source

0 ffffa18fa3d31b88 ffffff8003c33de63 nt!KeBugCheckEx+0x0

- 1 ffffa18fa3d31b90 fffff8003c34428f nt!VerifierBugCheckIfAppropriate+0xdf 2 ffffa18fa3d31bd0 fffff8003bd1625f nt!ViErrorFinishReport+0x117
- 3 ffffa18fa3d31c30 fffff8003c34e908 nt!ViErrorReport1+0x63
- 4 fffffa18fa3d31cd0 ffffff8003c343df0 nt!VfPnpVerifyIrpStackUpward+0x158
- 5 fffffal8fa3d31d30 ffffff8003c33d703 nt!VfMajorVerifyIrpStackUpward+0x74
- 6 ffffa18fa3d31d80 fffff8003c332776 nt!IovpCompleteRequest2+0xe3
- 7 ffffa18fa3d31df0 fffff8003bb208bd nt!IovpLocalCompletionRoutine+0x96
- 8 ffffa18fa3d31e50 fffff8003c332191 nt!IopfCompleteRequest+0x1cd
- 9 ffffa18fa3d31f60 fffff8003bc48d81 nt!IovCompleteRequest+0x1bd
- a fffffa18fa3d32050 ffffff8003e88b0fd nt!IofCompleteRequest+0x1286c1
 - b ffffa18fa3d32080 ffffff8003bb7e7ca HwUsbClient+0xb0fd
- c ffffa18fa3d32390 ffffff8003c331f49 nt!IopfCallDriver+0x56
- d fffffa18fa3d323d0 ffffff8003bc46441 nt!IovCallDriver+0x275
- e ffffa18fa3d32410 fffff80acd96d805 nt!IofCallDriver+0x12f0d1

f (Inline) -----

Wdf01000!FxIrp::CallDriver+0x23

10 (Inline) -----

 $\label{lem:wdf01000!FxIrp::SendIrpSynchronously+0xa0} Wdf01000!FxIrp::SendIrpSynchronously+0xa0$

```
11 ffffa18fa3d32450 fffff80acd96d2b1
Wdf01000!GetStackCapabilities+0x135
12 (Inline)
Wdf01000!FxPkgPdo::PnpQueryCapabilities+0x89
13 ffffa18fa3d324e0 fffff80acd962ef3
Wdf01000!FxPkgPdo:: PnpQueryCapabilities+0xb1
14 ffffa18fa3d325b0 fffff80acd961b72 Wdf01000!FxPkgPnp::Dispatch+0xb3
15 (Inline)
Wdf01000!DispatchWorker+0x9d
16 (Inline)
Wdf01000!FxDevice::Dispatch+0xbb
17 ffffa18fa3d32620 fffff8003e88cf8b
Wdf01000!FxDevice::DispatchWithLock+0x112
18 ffffa18fa3d32680 fffff8003e889642 HwUsbClient+0xcf8b
19 ffffa18fa3d32700 ffffff8003e88b085 HwUsbClient+0x9642
la ffffal8fa3d32780 fffff8003bb7e7ca HwUsbClient+0xb085
```

This thread is crashing

相关的问题组件

2: kd> lmvm hwusbclient Browse full module list

Loaded symbol image file: HwUsbClient.sys

Image path: \SystemRoot\System32\drivers\HwUsbClient.sys

Image name: HwUsbClient.sys

Browse all global symbols functions data

Timestamp: Tue May 14 18:02:33 2019 (5CDA9239)

CheckSum: 0002CA1C ImageSize: 00025000

Translations: 0000.04b0 0000.04e4 0409.04b0

下一步动作:

建议联系华为云桌面客户端厂商进行问题排查,谢谢

李琦 Li Qi 神州网信技术有限公司 C&M Information Technologies Co., Ltd. 服务电话: 4008180055

电子邮箱 Email: <u>liqi@cmgos.com</u>



发件人: Li Qi < liqi@cmgos.com > **发送时间:** 2020 年 8 月 18 日 18:34

收件人: 吴毓杰 <win10sup@sdc.icbc.com.cn>

抄送: Li Qi liqi@cmgos.com>

主题: [案例号: CAS-02812-Q3D7K7] % |P3||CBC|登录华为云桌面电脑蓝屏 % 初次响应

CMIT:0001728

吴毓杰 先生/女士, 您好!

感谢您联系神州网信技术支持中心。 我是技术支持工程师 李琦 。 很高兴能有机会协助您解决该问题。 您可随时通过邮件回复以及该问题事件号码 CAS-02812-Q3D7K7 与我联系。

如果您有任何其他疑问, 请随时与我联系。

此致,

敬礼

以上内容是一封有关向神州网信技术有限公司提交技术支持事件的邮件。

如果您希望本次回复能够被自动加入技术支持事件中, 您可以选择"全部回复"。