

Sunday Okewu

From: Olabode Oke
Sent: Friday, 14 August 2026 16:11
To: Sunday Okewu
Cc: Chris Ijeli; Temitope Odulate
Subject: RE: HYDROTEST TORQUE DRIIVE

Dear Sunday,

The maintenance team on site obviously didn't give you the update since morning.

Thanks for attending to it.

Regards,

Olabode Oke,
Senior Project Manager

From: Sunday Okewu <sundayokewu@dormanlongeng.com>
Sent: Friday, 14 August 2026 16:09
To: Olabode Oke <olabodeoke@dormanlongeng.com>
Cc: Chris Ijeli <chrisijeli@dormanlongeng.com>; Temitope Odulate <temitopeodulate@dormanlongeng.com>
Subject: RE: HYDROTEST TORQUE DRIIVE

Dear Bode,

You just brought this to my notice not up-to 30minutes ago and you are sounding as if we have discussed this since morning.

The ultimate should be to work as team and not blame game.

We will arrange for the replacement of the O-ring.

Best Regards,

Engr. Sunday Okewu Abba
Maintenance Manager



Dorman Long Engineering Limited

12/14 Agege Motor Road, Mushin, Lagos.

Tel: 234 8033628672

Email: sundayokewu@dormanlongeng.com

"We are committed to sustainability in every facet of our operations through improved performance, social responsibility, and corporate governance."

From: Olabode Oke <olabodeoke@dormanlongeng.com>
Sent: Friday, 14 August 2026 16:04
To: Sunday Okewu <sundayokewu@dormanlongeng.com>
Cc: Chris Ijeli <chrisijeli@dormanlongeng.com>; Temitope Odulate <temitopeodulate@dormanlongeng.com>
Subject: HYDROTEST TORQUE DRIIVE

Dear Sunday,

Please what is the plan to repair DLE torque that got faulty during operation since morning. The maintenance team has already checked.

Everyone is waiting. Thanks

Regards,

Olabode Oke,
Senior Project Manager