координатные точки

чистового колеса с черновой расточкой ступицы по чертежу KP-0050-16 rev.2 «ULT25»

Дата 18.07.2017 Овчинников А.С. тел. 74-74-805

Точка 1	Точка 9	Точка 17
x = 0.000000 mm	x = 338.778653 mm	x = 337.901095 mm
y = 0.000000 mm	y = 66.288259 mm	y = 90.457673 mm
Точка 2	Точка 10	Точка 18
x = 99.000000 mm	x = 367.892946 MM	x = 327.655955 mm
y = -24.500000 mm	y = 52.793345 mm	y = 99.698431 mm
Точка 3	Точка 11	Точка 19
x = 130.250000 mm	x = 386.642764 mm	x = 212.446335 mm
y = -24.500000 mm	y = 30.256615 mm	y = 99.816379 mm
Точка 4	Точка 12	Точка 20
x = 135.179945 mm	x = 394.750000 mm	x = 168.876306 mm
y = 6.626445 mm	y = 0.000000 mm	y = 80.564836 mm
Точка 5	Точка 13	Точка 21
x = 168.880557 mm	x = 460.250000 mm	x = 127.404772 mm
y = 51.523443 mm	y = -0.000000 mm	y = 116.826546 mm
Точка 6	Точка 14	Точка 22
x = 200.761567 mm	x = 394.750000 mm	x = 120.250000 mm
y = 66.082920 mm	y = 135.000000 mm	y = 162.000000 mm
Точка 7	Точка 15	Точка 23
x = 227.685009 mm	x = 394.750000 mm	x = 99.000000 mm
y = 86.097439 mm	y = 114.035264 mm	y = 162.000000 mm
Точка 8	Точка 16	
x = 312.314991 mm	x = 376.513347 mm	
y = 86.097439 mm	y = 86.437734 mm	

