## координатные точки

чистового колеса с черновой расточкой ступицы по чертежу КР-0008-18 тип ІВЕ 23

Дата 21.05.2018 Овчинников А.С. тел. 74-74-805

 Точка 1	 Точка 10	 Точка 19
x = 0.000000  mm	x = 359.946612 mm	x = 398.958421 mm
y = 0.000000 mm	y = 28.594430 mm	y = 117.847265 mm
-	•	•
Точка 2	Точка 11	Точка 20
x = 96.000000 mm	x = 399.429309  mm	x = 368.483524  mm
y = -53.625000 mm	y = 22.066554 mm	y = 56.622087 mm
Точка 3	Точка 12	Точка 21
x = 123.216599 mm	x = 407.999060  mm	x = 295.807626  mm
y = -53.625000 mm	y = 9.523305 mm	y = 56.805906 mm
Точка 4	Точка 13	Точка 22
x = 132.994431 mm	x = 408.529411  mm	x = 252.378623 mm
y = -45.721186 mm	y = 4.477358 mm	y = 95.225392 mm
Точка 5	Точка 14	Точка 23
x = 152.110632 mm	x = 413.502020  mm	x = 194.334885 mm
y = 43.447923 mm	y = 0.000000 mm	y = 114.849847 mm
Точка 6	Точка 15	Точка 24
x = 174.112904 mm	x = 461.000000  mm	x = 145.363323 mm
y = 76.810975 mm	y = 0.000000  mm	y = 130.161556 mm
_		
Точка 7	Точка 16	Точка 25
x = 232.297973 mm	x = 401.000000 mm	x = 139.088808 mm
y = 76.517018 mm	y = 135.000000 mm	y = 132.375000 mm
Точка 8	Точка 17	Точка 26
x = 282.676891 mm	x = 399.00000 mm	x = 96.00000 mm
y = 40.087877 mm	y = 133.00000 mm	y = 132.375000 mm
y - 40.08/8// MM	y – 155.000000 mm	y – 132.373000 MM
Точка 9	Точка 18	
x = 328.254845 mm	x = 399.00000 mm	
y = 25.881140 mm	y = 119.000000 mm	
, =====================================	,	
<i>26</i>	<i>25 24</i>	17 16

