

	1	1 a	2	3	4	5	6	7	
X	135.000	135.000	130.000	102.158	94.000	88.000	81.000	73.000	
Υ	-9.955	-5.705	-4.955	-0.779	-0.396	-0,285	-0,.219	-0.087	
R				204.34	364,74	6133.7	-538.08	-729.05	
	7 a	8	9	10	11	12	13	14	
X	70.000	64.000	57,000	51,000	47.000	43.000	41.000	39.000	
Υ	0.000	0.211	0.683	1.318	1.920	2.741	3.271	3.922	
R	-729.05	-207.72	-139.62	-93.31	-63.31	-46.32	-29.42	-18.03	
	15	16	17	18	19	19a	20	21	22
X	37.000	34.000	30.573	29.235	19.280	14.500	7.235	0.000	0.000
Υ	4.793	6.868	12.000	15.676	26.777	28.000	25.150	9.520	0.000
R	-13.58	-13.000		20.000	12.000	12.000	20.500		
–R по часовой стрелке									

Координатные точки профиля EN 13715 S 1002 h=28 e=31,5 15%