Visual Inspection of Motorcycle Connecting Rods

Marco Boschi – 0000829970 A.Y. 2018–2019

https://github.com/piscoTech/MotorcycleRods

1 Image Binarization and Labeling

The characteristics required to be extracted from the provided images are those computable via blob analysis, so the first step is to binarize the inherently binary images containing the rods.

The images are acquired with the backlighting technique so are suitable to be binarized using a single global threshold. Although the lighting is homogeneous in a single image, it is not consistent between different images making a fixed value for the threshold not a good choice so Otsu's algorithm has been deployed to find the optimal threshold using the function provided by OpenCV.

The results provided by Otsu's are almost perfect apart from some images in which very small holes appears and the rods are "broken", which seems caused by different surfaces of the rods appearing in the image, not just the top side. To fix this problem the image is further processed by a closing step using a 5×5 circular structuring element to reconstruct the rod.

Each image is then fed to the function provided by OpenCV to perform connected component labeling which is also capable of reporting the area and position, i.e. the barycenter, of each blob.

2 Rod Analysis

For each of the found components, which is sure to be a rod given the specification of the program, the corresponding rod type has to be found, which can be done by counting the number of holes.

This can be accomplished in three different ways: computing the Euler number of just the current rod, compute the contour hierarchy or labeling the background. Considering that for each hole is required the diameter and position and that the labeling function gives out of the box the position and the area, the latter option is chosen as the diameter of the circular hole will be computed with the inverse formula for the area of a circle.

The second labeling step is applied to the background and the found components will be the background of the scene, the rod itself and 1 or 2 circular blobs for the holes. The first two components are not interesting for determining the rod type so are discarded by checking whether the left- and top-most pixel coordinates are 0, a characteristic of the image background, and whether the blob center is the same as the center of the rod under analysis (this could also be done by checking for the same area as the holes are smaller than the rods). Both of these checks use only information provided by the labeling process so are not expensive.

After this second labeling the rod type can be identified and hole positions and diameters known.

2.1 Oriented MER

To compute rod width, height and width at the barycenter the oriented MER must be computed, so the first step is to find the rod orientation. OpenCV provides a function to compute the MER, but the one returned has minimum area, not minimum inertia with respect to the major axis.

Orientation is thus computed manually finding the axis with least inertia via the central moments computed by the appropriate OpenCV function. Once this is done the oriented MER can be computed by finding the contact points between the MER sides and the rod and then the sides themselves as the lines through the contact points with direction as the major and minor axes.

The contact points are found by scanning each pixel of the rod and recording those ones with the greatest positive and negative distance from the major axis, the same is done for the minor axis. Once the sides of the MER have been computed they can be intersected to find the vertices and thus the width and height of the rod.

The width at the barycenter is the length of the segment of the minor axis inside the rod itself and its two vertices can be found alongside the contact points by tracking those two points of the rod with the greatest positive and negative distance from the major axis and minimum distance from the minor axis, i.e. they are points of the minor axis so the distance is 0, but as there's no sub-pixel precision in finding these points the actual check is whether the absolute distance from the minor axis is less than 0.5. The width at the barycenter is then the distance between these two points.

3 Handling Distractors

Possible distractor objects are screws and washers with respectively 0 and 1 hole.

Given these characteristics, as the code to determine the rod type is based on the number of holes and already discards component with a number of holes different from 1 or 2, screws are already discarded out of the box.

When counting the number of holes the components (of the second labeling) with center equal to the one of the current component (of the first labeling) are discarded to ignore the rod itself. As the washer holes are exactly in the center this check also discards these holes and so also washers are already ignored out of the box because a rod with 0 "interesting" holes is not valid. If the hole was not in the center, a possible check to discard washers could be whether the elongatedness of the component is below a certain threshold.

4 Handling Iron Powder

To remove the unwanted iron powder from the image the right tool is opening, which must be deployed before the closing step used to fix rods broken by the binarization.

Structuring elements tested to remove the dust were a 5×5 circle, a 3×3 circle, a 2×2 circle and a 2×2 square, listed from worst to best. The larger structuring elements were more able to remove the dust from the binarized image, however as the parts of the rods around their holes are not thick enough the result contained damaged rods, which would render the following analysis meaningless. The actually used 2×2 square structuring element allows to remove most of the dust but not all and even if the rods are sometimes slightly broken the following closing step, still using a 5×5 circle, is able to repair them as if they were never broken.

The result of this process contains some false components consisting only of dust which will still be discarded as they have no holes, but the overall computation process will be drastically slowed down with no countermeasures in place, so when processing a component the first check is whether the area is below a certain threshold, if so it is immediately discarded and reported as dust, otherwise normal analysis will continue.