

DALMIA CEMENT (B) LIMITED - CEMENT PLANT **ARIYALUR ELECTRICAL MANUAL**



Rev. No: 02 ELEC/SOP/011 Issue No. 01 **Effective Date: 07.07.2017**

Approved By: HOD - ELECTRICAL Issued By: M.R

SOP for LRS Maintenance

: Describing LRS maintenance procedure to Electricians Scope

Responsibility : Electrical Engineer

Accountability : Section Head

PPE:

1. Nose mask

2. Goggles

3. Tested Electrical Rubber Hand Gloves

4. Cotton Gloves

5. Safety shoes

6. Safety helmet

Tools:

1. Paint brush

2. Hand Blower

3. Waste Cloth

4. Suitable spanner

5. Insulated Screw driver

6. Discharge Rod

Hazards:

Risk Associated

Electrical Shock

Minor body injury

Mitigating Measures

Tested Electrical Rubber Hand Gloves Safety shoes, gloves, helmet, goggles

Training needs:

- 1. Electrical shock recovery Training
- 2. Emergency preparedness
- 3. First aid training

Procedure:

- 1. Take the LOTO of the particular Motor Feeder (11KV HT Feeder) as per ELEC/SOP/001
- 2. Take the LOTO of the LRS Power Supply with as per ELEC/SOP/003.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR ELECTRICAL MANUAL



Issue No. 01Rev. No: 02Effective Date: 07.07.2017ELEC/SOP/011Issued By: M.RApproved By: HOD - ELECTRICAL

SOP for LRS Maintenance

- 3. Open the Doors in the LRS Panel and Clean. While cleaning use PPEs like Nose mask, goggles and hand Gloves.
- 4. Discharge the power terminals of LRS with discharge rod.
- 5. Check the Tightness of all LRS power terminal tightness. While doing the tightening handle the tools firmly.
- 6. Check the Condition of bushings for good condition. if not good, replace with new one.
- 7. Check the Water level in the LRS tank and top up if the level is less than the normal indicated level. For makeup water level, use proper instrument and avoid spillage of water in the ground.
- 8. Check the Power Connection Tightness of the Power Contactor of LRS short circuiting contactor. While doing the tightness, handle the proper tools firmly.
- 9. Open all the Power Contactors Arc Chute and Clean the Arc Chute, Fixed & Moving Contacts. While cleaning use PPEs like Nose mask, goggles and hand Gloves.
- 10. If the Condition of the Contact Kits is not good, replace with new Contact Kits.
- 11. Fix the Arc Chute and Check for Free Movement of the Moving Mechanism for all Contactors
- 12. Check the Control Wiring Tightness in the Resistance Panel & control panel with proper tool.
- 13. Clean the LRS Control Panel with hand blower / cloth. While cleaning use PPEs like Nose mask, goggles and hand Gloves.
- 14. Close the all panel doors and box up with Silicon Paste to restrict the dust entry.
- 15. Check the LRS box and control panel Body earthing.
- 16. Clear the LC as per ELEC/SOP/004 for the power supply of LRS.
- 17. Clear the LC as per ELEC/SOP/002 for the motor feeder and check the healthiness in the CCR. Take Trial if Possible and record all Check point in the concern Check list.

Emergency / Emergency Shut OFF:

1. If electrical shock injury or body injury is there, give First aid and inform to the Safety department or Call Emergency number 3108/9865152222/9750963761.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR ELECTRICAL MANUAL



Issue No. 01 Rev. No: 02 Effective Date: 07.07.2017 ELEC/SOP/011

Issued By: M.R Approved By: HOD - ELECTRICAL

SOP for LRS Maintenance

Records/Annexure:

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below.

JOB SAFETY ANALYSIS:(JSA)

Job Safety Analysis	Job: LRS maintenance	Date:	Analysis by:	Reviewed by:
Title of employee doing job: Electrician	Supervisor: Section Engineer	Department: Electrical	Section:	Approved by:

Reqd./recommended PPE: Nose mask, Goggles, Tested Electrical Rubber Hand Gloves, Cotton Gloves, Safety shoes, Safety helmet.

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Put on PPE, Take Permit				
Cleaning of Panels	Eye irritation,	Wear goggles	Damaged goggles/non standard goggles/ Not wearing goggle	Periodic replacement / Proper training/ Check before use
	Respiration problem	Wear Nose mask	Damaged nose mask/Not wearing Nose mask	Periodic replacement/ Proper training/ Check before use
	Body injury	Use Proper PPE	May be damaged	Tool box talk
		Use proper tools	Tools and material may slip	
Open the panel door. Discharge the panel terminals by discharge rod	Electrical shock	Use Tested Electrical Rubber Hand gloves	Damaged Gloves / Not checked before use	Periodic replacement/ To check for Damage before use
Check the tightness of Power and control terminals	Body injury	Use proper tools	Nonstandard /damaged tools	Training for tools handling/ Periodic replacement
		Wear safety helmet, safety shoes , hand gloves	Tools and material may fall on human body	Without PPE don't perform the job
Check Short circuit contactor	Body injury	Use proper tools	Nonstandard /damaged tools	Periodic replacement. Tool box training
		Wear safety helmet, safety shoes , hand gloves	Tools and material may fall on human body	Periodic replacement.