DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - DALMIAPURAM



PRODUCTION DEPARTMENT

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/PROD/18

Issued By: S & P Approved By: Head – Production

SOP FOR RAW MEAL BLENDING & FEEDING TO FLS KILN

SCOPE : RAW MEAL BLENDING & FEEDING TO FLS KILN

RESPONSIBILITY: CCR executive.

Accountability: Section Head – Pyro.

PPE:

1. Safety goggles,

- 2. Safety helmet,
- 3. Safety shoe,
- 4. Mask,
- 5. Cotton Gloves.
- 6. Safety harness(Full body)

TOOLS:

- 1. Poking bar,
- 2. Hammer.
- 3. showel

Hazard:

Risks associated: Mitigating Measures

Fall from height, Use of safety harness

Fall of tools; Carry the tools in tool bags

Hit of Hammer in hand; Trained to be engaged

Procedure:

- 1. Check the silo level & raw meal values of silo.
- 2. Get the clearance from VRM-III M/A as per Work Instruction for extracting raw meal from the silo in accordance to Work Instruction.
- 3. Start Feed Group 43N with SFF1/SFF2 in circuit, depending upon the availability, in recirculation mode at around 100 tph and ensure all the drives are running.



DALMIA CEMENT (B) LIMITED - DALMIAPURAM

Palmia

PRODUCTION DEPARTMENT

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/PROD/18

Issued By: S & P Approved By: Head - Production

SOP FOR RAW MEAL BLENDING & FEEDING TO FLS KILN

- 4. Start extraction group 41N and ensure all the drives are running.
- 5. Check and ensure raw meal is extracted from silo, filled in the control bin and recirculated
- 6. When the Kiln becomes ready to take feed, deselect the "Recirculation" key and ensure the feed gets diverted to preheater automatically.
- 7. Monitor the filling and discharge of control bin for proper working.
- 8. Regulate the feed rate accordingly to Kiln / P.H. condition.
- 9. Inform the Chemist in shift about extraction from silo.
- 10. Ensure that the initial and final raw meal flow counter readings are automatically recorded in the Kiln Log sheet. In case of any problem in auto recording, inform the concerned engineers and record manually till the problem is rectified.

Job Safety Analysis	Job: RAW MEAL BLENDING & FEEDING	Date: 01 – 09 - 2013	Analysis by: Section Incharge	Reviewed by: Section Head				
Title of employee doing job:	Supervisor: Sec. Incharge	Department: Production	Section: Pyro	Approved by: Department Head				
Req'd/recommended PPE:								
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action				



DALMIA CEMENT (B) LIMITED - DALMIAPURAM



PRODUCTION DEPARTMENT

Issue No. 02	Rev. No: 01	Effective Date: 22.05.2015		SOP	/PROD	/18
Issued Bv: S & P			Approved By: Head - Pro	oduct	ion	

SOP FOR RAW MEAL BLENDING & FEEDING TO FLS KILN

Cleaning of raw meal dust spillage	Hot material cause burn injury	Use hand gloves and showel for cleaning hot powder	Hot powder may entrapped into shoes	Use proper safety asphestos PPE's

Emergency Shut- off:

1. If body injury is there, First aid will be given and inform to the Safety department or Call Emergency number 233/555/9865125176/9865177444.

HOD PRODUCTION

HOD TECHNICAL