

DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION MANUAL



Issue No. 01	Rev. No: 02	Eff	fective Date: 20.09.2017	INST/SOP/029
Issued By: M.R			Approved By: HOD - INST	RUMENTATION
SOP for bypassing the interlock				

- 1 If any disturbance in the Process / Field Signals CCR Executives will inform to concern Shift Engineers.
- 2 If any requirement for bypass the interlocks, the respective Shift Engineers will inform to respective Section Heads / Shift Managers.
- 3 The Section Head / Shift Manager will authorize to bypass the interlocks through Instrumentation Shift Engineer.
- 4 Interlock bypass information will be register in the bypass register as per IMS Register No: 56.
- 5 Instrumentation Shift Engineer will normalize the interlock bypass after getting the information from concern Section Head / Shift Manager.
- 6 The interlock bypass normalization will be update in the bypass register as per the IMS Register No: 56