

DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION MANUAL

INSTRUMENTATION MANUAL

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/INST/35

Issued By: M.R Approved By: HOD - INSTRUMENTATION

SOP for Checking and Maintenance of Weigh bridges

Scope: Checking and Maintenance of Weigh Bridge

Responsibility: Instrumentation technician.

Accountability: Instrumentation - Section Engineer.

PPE:

- Safety helmet
- Safety shoe
- Mask
- Goggles
- Hand gloves

Tools required:

- Multimeter
- Insulated Screw Driver
- Hand Blower
- Ring spanner

Hazard Analysis:

Risks associated Mitigating Measures

Electrocution Use Insulated hand glove and Tools

Hand injury Use proper tools &tackles, Hand gloves



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION MANUAL

INSTRUMENTATION MANUAL

Issue No. 02Rev. No: 00Effective Date: 01.11.2019SOP/INST/35Issued By: M.RApproved By: HOD - INSTRUMENTATION

SOP for Checking and Maintenance of Weigh bridges

Procedure:

- 1. Use PPE's like nose mask, goggles.
- 2. Before starting the job, take the work permit.
- 3. Before starting the Maintenance inform to the weigh bridge Operator and ensure the truck movement stopped.
- 4. Keep the Man working Sign Board towards the vehicle Entry.
- 5. Remove the inspection plates for checking the Load cells.
- 6. Clean the load cells and mounting pads with help of blower.
- 7. Check the load cell cable condition and if there is any twist in the cable release the same by removing the load cell.
- 8. Before removing the load cell Use proper capacity Jack and wooden slipper plates for lifting/locking the weighbridge platform.
- 9. Check the Grease retainer cup condition and fill the grease while removing the cups.
- 10. Check the load cell mounting buttons condition and replace if there is any wear and tear.
- 11. After lowering the platform, check the platform movement and it should oscillate with touching the stationary parts.
- 12. Clean the load cell JB and Controller with blower.
- 13. Check the Load cell earthing cable tightness and measure the Resistance values between platform and earth pit. It should be near to zero.
- 14. Check the tightness of the connections with proper insulated tools.
- 15. Return the work permit after job completion.
- 16. Give the clearance for the weighbridge operation.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION MANUAL

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/INST/35

Issued By: M.R Approved By: HOD - INSTRUMENTATION

SOP for Checking and Maintenance of Weigh bridges

Emergency / Emergency Shut OFF:

1. If any requirement of First aid during the work,inform to the Safety department or Call Emergency number 3108/9865152222/9750963761.

Records/Annexure:

1. JSA as enclosed below.

JOB SAFETY ANALYSIS :(JSA)

JOB SAFETY A	ANALYSIS :(JSA)						
Job Safety Analysis	Job: Checking and Maintenance of Instrumentation panels	Date:20-09-2017	Analysis by: Section Engineer	Reviewed by: Section Head			
Title of employee doing job: INST - TECHNICIAN	Supervisor: SECTION ENGINEER	Department: INSTRUMENTATION	Section: Crusher And Packing Plant	Approved by: HOD			
Req'd/recommended PPE: SAFETY HELMET, SAFETY SHOES, GOGGLES, DUST MASK, HAND GLOVES							
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action			
Place the Men Working Board.	Fall on Leg	Wear Safety Shoes	Leg Injury	Ensure the PPE Conditions before Wear			



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR

INSTRUMENTATION MANUAL

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019 SOP/INST/35					
Issued By: M.R Approved By: HOD - INSTRUMENTA				RUMENTATION			
SOP for Checking and Maintenance of Weigh bridges							