# **Dalmia**BHARAT CEMENT

## **DALMIA CEMENT (B) LIMITED - Ariyalur**

## **MECHANICAL SOP**

Issue No. 02 Rev. No: 00 Effective Date: 1.11.2019 SOP/MEC/024

**Issued By: M.R Approved By:** HOD-Mechanical

## **RABH BAG REPLACEMENT.**

**Scope:** To replace RABH bag Responsibility: Engineer/SH

#### PPE:

- 1. Safety helmet
- 2. Safety shoe
- 3. Mask
- 4. Safety goggles
- 5. Gloves

#### **TOOLS:**

- 1. Screw driver
- 2. spanner set
- 3. 24v lamp
- 4. Crow bar
- 5. Nylon rope

#### **Hazard Analysis:**

<u>Risks associated:</u> <u>Mitigating Measures</u>

**Excessive temperature** Use Apron

Dust emission control the inlet damper before entering

#### **Procedure:**

- 1. Isolate the chamber whose differential pressure was low, by closing inlet valve.
- 2. Close the reverse poppet & outlet poppet valve by mechanical isolation.
- 3. Open the chamber inspection/manhole doors at bottom side.
- 4. After ensuring cold condition of the chamber.
- 5. Give clearance for the working crew.
- 6 .Thoroughly check for the damaged bags.
- 7. Don't allow the maintenance crew to carry sharp edged tools inside the chamber.
- 8. Use 24 volts lights for checking of damaged bags.

# **Dalmia**BHARAT CEMENT

## **DALMIA CEMENT (B) LIMITED - Ariyalur**

### **MECHANICAL SOP**

Issue No. 02 Rev. No: 00 Effective Date: 1.11.2019 SOP/MEC/024

**Issued By: M.R Approved By:** HOD-Mechanical

### **RABH BAG REPLACEMENT.**

- 9. Locate the damaged bags by the presence of accumulated dust nearby.
- 10. Remove the bottom clamp and top tension hook of the damaged bags.
- 11. Don't keep bags separately on the ground/Open area as the bags are sensitive rough surface/tools.
- 12. Bring only required quantity of bags in box to the chamber.
- 13. First fit the bottom clamp in such away the double fold should cover the ventury tight.
- 14. Top hook to be tightened with tensioning tool.
- 15. Applying pressure required is 3.0-3.5 bar.
- 16. Check the stitching portion of the bag come in line with adjacent the proper fixing of the bags at same height.
- 17. After replacing the damaged bags, check the chamber thoroughly.
- 18. Close the man hole / inspection door after removing the all tools and persons.
- 19. Open the inlet, outlet & reverse poppet valves openings for putting the chamber to normal operation.
- 20. Intimate the CCR personnel.
- 21. Maximum two chambers can be attended at a time without hampering the normal operation of the reverse air bag house performance.

#### **Emergency / Emergency Shut OFF:**

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

#### **Records/Annexure:**

Refer LOTO standards/permit & JSA is enclosed below.

**JOB SAFETY ANALYSIS : ( JSA)** 



# **DALMIA CEMENT (B) LIMITED - Ariyalur**

## **MECHANICAL SOP**

Issue No. 02 Rev. No: 00 Effective Date: 1.11.2019 SOP/MEC/024

Issued By: M.R Approved By: HOD-Mechanical

## **RABH BAG REPLACEMENT.**

Job Safety Analysis	Job: Replacement of Expansion joint	Date: 01 – 09 - 2014	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job : Section engineer	Supervisor: Section Engineer	Department: Mechanical	Section: All Section	Approved by: HOD Mechanical
Reqd./recommended PPE's : Safety Helmet,				

Reqd./recommended PPE's: Safety Helmet, Safety shoe, Hand Gloves, Safety goggles. Nose mask.

SI. No	Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What could go wrong	Corrective action
1	Close the inlet manual damper	Injury in hand	Use proper PPE	Injury by slip of chain	Allot trained workers to close the inlet damper
2	Closing the poppet valves	Release of pressurized air	Lock the poppet valve by mechanical stopper	Sudden release of poppet valves while working	Arrest the pneumatic valves
3	Open the chamber	Fall of door & injury	Use proper PPE & tools	Impact of door on workers while opening	Use crow bars for opening
4	Crew entry	Poor visibility	Ensure illumination more than 50 lux to ensure clear vision while working at night.	Less illumination- Strain for workers	Use 24V light
5	Locate the damaged bag	slip and fall of person, fall of material	Before starts of work (i.e.climbing) ensure that your shoes are free from oil grease or other slippery materials.	Slip of man	Check for working platform before entry
6	During working chamber	Fall of material (bag)	Ensure that there is no simultaneous working is done below and ensure proper virtual barrication while bag is being lifted	Bag falling over worker	Tie the end of the bag with proper loacking system in the top



# **DALMIA CEMENT (B) LIMITED - Ariyalur**

## **MECHANICAL SOP**

Issue No. 02 Rev. No: 00 Effective Date: 1.11.2019 SOP/MEC/024

Issued By: M.R Approved By: HOD-Mechanical

# **RABH BAG REPLACEMENT.**

7	Tensioning the bag	Leak of clamp	Ensure proper clamping	Hit of pressurized hose	Fasten the hose with the tensioning tool with proper clamps
8	Closing the doors	Fall of door & injury	Use proper PPE & tools	Impact of door on workers while closing	Use crow bars for opening
9	Release the air pressure & open the inlet & poppet valves	Hit of pressurized hose	Clamp the hose & release the air	Sudden release of air on workers	After fastening the hose release the hose slowly



# **DALMIA CEMENT (B) LIMITED - Ariyalur**

## **MECHANICAL SOP**

Issue No. 02Rev. No: 00Effective Date: 1.11.2019SOP/MEC/024Issued By: M.RApproved By: HOD-Mechanical

# **RABH BAG REPLACEMENT.**

S L N o	Activity		Tag / Name of the Equipment			
			Isolation Type			
			Electrical Energy	Other Energy		

RAW MILL BAG HOUSE BAGS REPLACEMENT	NAME AND TAG FOR THE	421FN1 RAW MILL BAG HOUSE FAN	361LD3 BY- PASS DUCT DAMPER IN CLOSED CONDITION	361FN3 RAW MILL FAN	POPPET DAMPERS COMPRESSOR COMMON AIR LINE VALVE TO BE CLOSED
	EQUIPMENT	421FN2 REVERESE AIR FAN	BAG HOUSE BOTTOM ROTARY AIR LOCK		