

DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM



Issue No. 01 Rev. No: 00 Effective Date: 01.03.2016 SOP/Elect /24

Issued By: S & P Approved By: Elect. & Inst Head

SOP For Underground cable trench inspection

Scope/Purpose: This Procedure to establish and ensure safe method of Underground cable trench

inspection.

Responsibility : Section Supervisor – Electrical

Accountability: Head-Electrical

PPE:

1. Safety shoe/Boot,

2. Safety Helmet

3. Rubber Gloves

Tools:

1. Insulated tools

2. 24V Lamps

Hazard Analysis:

Risks associated Mitigating Measures

Electric shock Usage of insulated tools

Presence of Toxic gas Measurement of Oxygen level.

Man entry hole blockage Alternate man entry hole in good condition.

Presence of insects / snake Minimum 2 trained person should enter the tunnel.

Training needs:

- 1. Usage of tools and Nature of Hazards
- 2. Usage of PPEs

Procedure:

- a) Get work permit (CSE Permit) from the concerned Electrical section in-charge.
- b) Illuminate the trench with 24V lamps.
- c) Ensure the ventilation / exhaust fan running for the trench.
- d) Ensure the trench is de-watered properly.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM



Issue No. 01 Rev. No: 00 Effective Date: 01.03.2016 SOP/Elect /24

Issued By: S & P Approved By: Elect. & Inst Head

SOP For Underground cable trench inspection

- e) Enter into the trench through proper entry point only.
- f) Inspect the cables & trays for healthiness.
- g) Fill the check list.
- h) Ensure all opening holes are properly closed after inspection.
- i) Return the Work permit.

Emergency / Emergency Shut OFF:

1. If any injury is there, and inform to the safety department or call Emergency number 251 / 254 / 568 /9842994062.

Records/Annexure:

1. JSA is enclosed below.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM



Issue No. 01 Rev. No: 00 Effective Date: 01.03.2016 SOP/Elect /24

Issued By: S & P Approved By: Elect. & Inst Head

SOP For Underground cable trench inspection

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: Underground cable trench inspection	Date:	Analysis by:	Reviewed by:
Title of employee doing job: Electrician	Supervisor: Section Supervisor	Department: Electrical	Section: Plant	Approved by:
Req'd/recommended PPE: Safety shoe, safety helmet & Rubber Gloves.				
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Entry into the trench Inspection of cables	Suffocation Electric shock	Ensuring Oxygen level & proper ventilation Usage of Insulated tools. Usage of Hand gloves	Error in Oxygen level measurement Insulation failure in tools	Usage of good condition and valid tested instruments Usage of good condition and valid
Checking Trays/cables	Fall from height / Slippery	Usage of ladders	Ladder collapse	Usage of good condition and valid tested instruments
Working in tunnel for cable inspection	Earth material surging and closing the man hole	Man holes to be properly constructed and no temporary man hole to be used.	Edge may collapase	Quality construction to be done.