DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01Rev. No: 02Effective Date: 17.10.2017SOP/MEC/083Issued By: M.RApproved By:

SOP FOR TRAVESE DRIVE WHEEL

- 1. Take the line clearance. Use LOTO system
- 2. The line clearance paper should be with the person who is working in the site.
- 3. Use ppe's while working
- 4. Remove front plate by removing the bolts.
- 5. Remove gear lock plates.
- 6. Drain the gear box oil.
- 7. Remove top cover of gear box.
- 8. Taken down gear box bottom cover with gear.
- 9. Remove gear and shaft assembly.
- 10. Fix 2 nos. jacks for bogie lifting.
- 11. Remove wheel lock plate.
- 12. Lift the bogie.
- 13. Remove the wheel form bogie.
- 14. Installer new wheel Assembly.
- 15. Lubricate the both bearings.
- 16. Lower down the bogie.
- 17. Fix the wheel lock plate.
- 18. Insure the lock plate bolt tightens.
- 19. Re assembles the Pinion shaft.



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01	Rev. No: 02	Effective Date: 17.10.2017		SOP/MEC/083
Issued Bv: M.R			Approved By:	

SOP FOR TRAVESE DRIVE WHEEL

- 20. Align the pinion shaft with gear box end cover.
- 21. Removed the jack and lower down the wheel assembly.
- 22. Fix the gear box top cover.
- 23. Tighten all housing bolt.
- 24. Top up the oil as per level.
- 25. Weld all side plate and fix front plate.
- 26. Ensure lubrication of pinion and gears.
- 27. Clear the shut down.
- 28. Remove all tools tackles and all unwanted materials.
- 29. Take the trial in local for free movement of wheel.