

Issue No. 02

## DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM



SOP/INST/01

INSTRUMENTATION DEPARTMENT

**Effective Date: 22.05.2015** 

Issued By: S & P Approved By: Elect. & Inst Head

**SOP FOR TESTING / CALIBRATION OF INSTRUMENTS** 

**Scope/Purpose**: This SOP is applicable to Safe working for Testing and calibration of

Instruments.

**Rev. No: 01** 

**Responsibility**: Instrument Mechanic / Supervisor

**Accountability** : Section In-Charge

PPE:

1. Hand gloves

2. Safety Shoes

#### Tools:

1. Insulated Spanners / Tools

2. Multimeter / Ammeter / Calibrators

### **Hazard Analysis:**

### Risks associated Mitigating Measures

Electric shock Usage of Insulated tools and Safety shoes

### **Training needs:**

- 1. Emergency preparedness
- 2. First aid procedure
- 3. Calibration procedures

#### **Procedure:**

- 1. Use Proper PPE & tools
- 2. Take proper work permit from section in-charge as per the work condition.
- 3. Ensure Room lighting is good.
- 4. Ensure Multimeter / ammeter / Calibrator selection are correct.
- 5. Ensure the Trip protection for the testing circuits.



# DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM INSTRUMENTATION DEPARTMENT



Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/INST/01

Issued By: S & P Approved By: Elect. & Inst Head

**SOP FOR TESTING / CALIBRATION OF INSTRUMENTS** 

- 6. Test / calibrate the instruments as per testing / calibration procedure.
- 7. During testing avoid improper connections.
- 8. Don't allow unauthorized persons near work area.
- 9. After the job completion isolate the instruments from power supply.

### **Emergency / Emergency Shut OFF:**

1. If electric shock is there, First aid will be given and inform to the Instrumentation department or Safety department or Call Emergency number 245 / 567 / 222 / 98651 77444.

### **Records/Annexure:**

- 1. Refer Line clearance in Instrumentation department.
- 2. JSA is enclosed below.



# DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM INSTRUMENTATION DEPARTMENT



Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/INST/01

Issued By: S & P Approved By: Elect. & Inst Head

**SOP FOR TESTING / CALIBRATION OF INSTRUMENTS** 

### **JOB SAFETY ANALYSIS: (JSA)**

Job Safety Analysis	Job: Testing / Calibration of instruments	Date: 15 – 06 - 2012	Analysis by:	Reviewed by:
Title of employee doing job: Instrument Mechanic	Supervisor: Section Engineer	Department: Instrumentation	Section: Instrument Lab	Approved by:
Req'd/recommended PPE: Insulated Tools, Safety shoes				
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Switch ON the connected circuit	Electric shock	Ensure proper wiring & connections	Wrong connections	Wiring as per the drawing & ensure trip protection
Touching the connected probes / instruments	Electric shock	Switch OFF the circuit before touching	Electrostatic discharge / Improper electrical insulation	Discharge time to be maintained for capacitors / Use of proper instruments

HEAD E & I HEAD TECHNICAL