

DALMIA CEMENT (B) LIMITED - DALMIAPURAM



MECHANCAL DEPARTMENT

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MECH/43

Issued By: S & P Approved By: Head- Mech

SOP for Mechanical Preventive & Breakdown Maintenance

SCOPE: Preventive & Breakdown maintenance

RESPONSIBILITY: Section Engineers

Accountability: Section Heads – Mechanical maintenance

PPE:

1. Safety goggles,

- 2. Safety helmet,
- 3. Safety shoe,
- 4. Mask,
- 5. Cotton Gloves.
- 6. Safety harness(Full body)

TOOLS:

- 1. Spanners set.
- 2. Lifting tools & tackles.
- 3. Special tools
- 4. Wooden sleepers
- 5. Belt conveyor sheets

Hazard:

Risks associated: Mitigating Measures

Fall from height, Use of safety harness

Fall of tools; Carry the tools in tool bags

Hit of Hammer in hand; trained to be engaged

Slippery due to oil wearing shoes and careful walk

Spray of coolant to eyes using of goggles

Battery acid spillage using PPE like gloves, goggles and face mosque

Procedure:

Preventive Maintenance

1. Decide equipment to be taken for preventive maintenance based on schedule



DALMIA CEMENT (B) LIMITED - DALMIAPURAM

MECHANCAL DEPARTMENT



Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MECH/43

Issued By: S & P Approved By: Head- Mech

SOP for Mechanical Preventive & Breakdown Maintenance

- 2. Get clearance from production department
- 3. Prepare list of tools& tackles required for attending maintenance.
- 4. Check the condition of tools and tackles to be used for safe use
- 5. Ensure the lifting tools are tested and certified
- 6. Ensure trained employees or contractors are deployed for the job
- 7. Ensure employees holding valid permit
- 8. Ensure relevant work permit is taken for the job
- 9. Ensure LOTO is taken for the equipment on which maintenance is taken
- 10. Ensure all other connected energy sources are isolated.
- 10. Use only full body harness while working at height
- 11. Follow relevant SOP for the job.
- 12. Clear all used oil, filters from the area after completion of job
- 13. Use only 24V hand lamps in during the maintenance
- 14. Clear work permits after completion of job
- 15. Ensure gas cylinders & cutting torches are equipped with flash back arrester
- 16. Ensure hand tools are in good condition
- 17. Ensure safe usage of hand tools

Emergency Shut- off:

1. If body injury is there, First aid will be given and inform to the Safety department or Call Emergency number 233/555/9865125176/9865177444.

Records/Annexure:

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below.



DALMIA CEMENT (B) LIMITED - DALMIAPURAM



MECHANCAL DEPARTMENT

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MECH/43

Issued By: S & P Approved By: Head- Mech

SOP for Mechanical Preventive & Breakdown Maintenance

Job Safety Analysis	Job: DG SET Preventive maintenance	Date: 25 – 06 - 2013	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job:	Supervisor: Sec.Engr	Department: Mechanical	Section: All equipments	Approved by: Department Head
Req'd/recommended PPE:				
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Working at Height	Fall from height	Follow work at height SOP	Not following procedure	Ensure SOP is followed before work is started
Working on electrical driven equipment	Electrical shock / accidental start of equipment	Follow LOTO	Not adhering to standard	Ensure LOTO before starting job.
Using lifting tools & tackles	Fall from height/ hit injury to body parts	Ensure certified tools & tackles are used. Don't over load	Overloading	Ensure lifting tools are nor overloaded
Usage of hand tools	Injury to fingers / hands	Follow SOP for safe usage of hand tools	Not following SOP	Ensure right tools are used right job in right method
Checking the battery electrolyte	Injury to hands / eyes	Use proper ppe	Not following the methods	Follow the right method and procedure
Handling the oils	Slippery of persons	Collect the oil in a bucket to avoid the spillage	Not following the system	Ensure the oil to be collected in the buckets and later it is to poured in the old oil barrels

HEAD MECHANICAL

HEAD TECHNICAL