DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01	Rev. No: 00	Effe	ctive Date: 1.04.2018	SOP	/MEC/	/149

Issued By: M.R Approved By: HOD -Mechanical

SOP FOR PIPE LINE REPLACEMENT WORK

SCOPE: PIPE LINE REPLACEMENT WORK (AIR & WATER)

Responsibility: <u>Mechanical-Section Engineer</u>
Accountability: <u>Mechanical-Section Head</u>

PPE:

1. Safety helmet.

2. Safety shoe.

3. PPE kit.

TOOLS:

- 1. Ring & DE spanner set.
- 2. Pipe wrench.
- 3. Chain block.
- 4. Manila / Nylon rope.
- 5. Pipe
- 6. Ball pin Hammer
- 7. Chipping Hammer

Hazard Analysis:

Risks associated: Mitigating Measures

Heavy Material : Use of Chain blocks & Ropes

PURPOSE: To lay down a procedure to describe the stops to be followed and persons involved in the maintenance of water & air line replacement work.

PROCEDURE:

- 1. Take the electrical permit for respective pipe line pumps and compressor.
- 2. Take the isolation valves LOTO permit & fixed the LOTO lock & Tag
- 3. Drain the all pressure in that line.
- 4. Take the General work permit & Hot work permit, if required take the Height work permit
- 5. Insure for proper PPE (PVC hand glouse / others)
- 6. Insure the cutting set and welding machines.

DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01	Rev. No: 00	Effective Date: 1.04.2018		SOP/MEC/149	
Issued By: M.R			Approved By: HOD -Mec	hanical	
SOP FOR PIPE LINE REPLACEMENT WORK					

- 7. Insure the proper holding arrangement for old pipe lines and existing lines.
- 8. Cut and remove the which pipe line potion to be removed.
- 9. Existing pipe line surface to be cleaned and grinding to be done.
- 10. Proper tools & tackles to be using for re erected the new pipe lines (if required use the chain block or crane).
- 11. check the straight line and alignment of pipe line and take the stitch welding for different places.
- 12. Full welding to be done.
- 13. After welding temperature gone to normal we can take the welding inspection.
- 14. Checking purpose to take the temporarily energization & re-isolation removal take the permission from section Head.
- 15. After taking of energization to start the pumps/compressor/valve to be open
- 16. Check all the welding points and threading points if any leakages is there.
- 17. If any leakages is there take the re-isolation and leakages to be arrested.
- 18. If no leakages to take the re-isolation and close the work permit.
- 19. After closing the work permit Energy isolation permit to be closed.
- 20. And inform to control room operator/ system put in to operation.

Job Safety Analysis:

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job	What Could Go Wrong	Corrective Action		
Required /recommended PPE: Safety Helmet, Safety shoe, Hand Gloves, Safety goggles and Nose mask.						
Title of employee doing job: Fitter	Supervisor: Section Engineer (Mech.)	Department: Mechanical	Section:Utility	Approved by: G.Shankarappa		
Job Safety Analysis	Job: Pipe line modification	Date: 01/04/2018	Analysis by: A.Narendhra babu.	Reviewed by: K. Sathish Kumar.		



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01 Rev. No: 00 Effective Date: 1.04.2018 SOP/MEC/149

Issued By: M.R Approved By: HOD -Mechanical

SOP FOR PIPE LINE REPLACEMENT WORK

Depressurization	Material damaged or person injured	Depressurized the pipe line first by using the vent valve open condition	Without depressurized pipe line cutting it will make harmful to the equipment as well as person also	Use the drain valve to be open condition
Old pipe line removal	Material fall down	Provide the necessary lifting/ holding arrangement for the pipe line	Manually holding the pipes it may fall down and damaged material & injured the person	Put chain block or other lifting devices to be used.
New pipe line erection	Material fall down	Provide the necessary lifting/ holding arrangement for the pipe line	Manually holding the pipes it may fall down and damaged material & injured the person	Put chain block or other lifting devices to be used.