# **Dalmia**BHARAT CEMENT

## **DALMIA CEMENT (B) LIMITED - Ariyalur**

#### **MECHANICAL SOP**

Issue No. 02 Rev. No: 00 Effective Date:01.11.2019 SOP/MEC/034

Issued By: M.R Approved By: HOD-Mechanical

## SOP FOR WEIGH FEEDER PULLEY REPLACEMENT

Scope: To replace Weigh feeder pulley

**Responsibility:** Engineer/SH

#### PPE:

- 1. Safety helmet
- 2. Safety shoe
- 3. Safety goggles
- 4. Gloves

#### **TOOLS:**

- 1. spanner set
- 2. chain blocks
- 3. Slings
- 4. D-shackles

#### **Hazard Analysis:**

Risks associated: Mitigating Measures

Fall of pulley Use correct tools to remove and fixing

Fall of tools, Carry the tools in tool bags

#### **Procedure:**

- a. Take LOTO for the weigh feeder
- b. Loose the Take-up bolts completely.
- c. Remove the skirt rubber and top hood.
- d. Arrange chain block.
- e. Remove old pulley with proper arrangements
- f. Change the new pulley.
- g. Arrange top hood and skirt rubber.
- h. Give proper tension by tightening the belt
- i. Remove chain block and all things.



## DALMIA CEMENT (B) LIMITED - Ariyalur

#### **MECHANICAL SOP**

Issue No. 02 Rev. No: 00 Effective Date:01.11.2019 SOP/MEC/034

Issued By: M.R Approved By: HOD-Mechanical

## SOP FOR WEIGH FEEDER PULLEY REPLACEMENT

- j. Clear the LOTO clearance for weigh feeder drive.
- k. Intimate CCR to be in local mode and to make adjustment of belt to run at center.
- l. When belt obtain center position then instrumentation calibration has to be done.
- m. Once the calibration is completed then give clearance for sequence mode.

#### **Emergency / Emergency Shut OFF:**

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222.

### **Records/Annexure:**

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below

## **JOB SAFETY ANALYSIS: (JSA)**

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: Weigh Feeder Belt Pulley Replacement	Date: <b>01/09/2014.</b>	Analysis by: Section Engineer	Reviewed by: Section Head.							
Title of employee doing job: Site in charge (Shree)	Supervisor: Section Engineer	Department: Mech.	Section: Cement Mill	Approved by: HOD-Mechanical							
Req'd/recommended PPE: Safety helmet, Safety shoe, Safety goggles & Asbestos Gloves.											
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action							
Removal of Safety guard, Skirt rubber, Side skirt And Support for weigh feeder	Hand injury Leg injury	Use proper lifting tools to lift the material	Material may slip during removing	Ensure the person Lifting the material as per lifting procedure							
Position of the chain blocks for lifting the weigh feeder for removing old pulley and inserting new pulley	Leg and hand injury	Use correct lifting Tackles wire rope slings	Chain block may slip and fall while removing and inserting the pulley	<ol> <li>Check the condition of the ropes and slings</li> <li>Check the correct size of slings to operate/actual capacity and ensure certificate of clearance</li> </ol>							



## **DALMIA CEMENT (B) LIMITED - Ariyalur**

## **MECHANICAL SOP**

Issue No. 02 Rev. No: 00 Effective Date:01.11.2019 SOP/MEC/034

Issued By: M.R Approved By: HOD-Mechanical

# **SOP FOR WEIGH FEEDER PULLEY REPLACEMENT**

SL No	Activity		Tag / Name of the Equipment Isolation Type					
			Electrical Energy	Other Energy				
	•							

10										
19					Feeding					
		Name and	'		Conveyor					
	Weigh	Tag for			for the same					
	Feeder Belt	the		Related	Related					
	Replacement	Equipment	4	Drive	Hopper.					