DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL

Issued By: M.R Approved By: HOD-Mechanical

SOP FOR INSPECT GAS CUTTING SET & WELDING CABLE

SOP FOR INSPECT GAS CUTTING SET & WELDING CABLE

Scope : This SOP is applicable for inspect gas cutting set & welding cable.

Responsibility : Tool room operator

Accountability : Section Engineer.

PPE:

1. Safety helmet,

- 2. Safety shoe
- 3. Safety Belt
- 4. Nose Mask.
- 5. Asbestos Gloves.

Training needs:

- 1. Emergency preparedness
- 2. Fire Fighting

Procedure:

- 1) Check for Hoses color code blue for oxygen and orange for LPG.
- 2) Inspect hoses free from cuts, cracks, burnt or worn places.
- 3) Do not repair leaking hoses with tape. Splice in a new piece of hose or discard. When splicing a hose,
- 4) Check for standard brass splicing nipples
- 5) Ensure that all fittings are free of oil.
- 6) Check for Standard Hose Clamps are used & avoid ordinary wire to clamp the hose to a connector.
- 7) Check Oxygen and LPG regulator for leaks.
- 8) Both gauges on regulator should be working condition

DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL

Issue No. 01 Rev. No: 00 Effective Date: 28.02.2018 SOP/MEC/144

Issued By: M.R Approved By: HOD-Mechanical

SOP FOR INSPECT GAS CUTTING SET & WELDING CABLE

- 9) Check regulator free from cuts, cracks, burnt or worn places.
- 10) Check for Standard Messer Make flash back arrester on the both end of torch and regulator side.
- 11) Inspect welding cable & holder free from cuts, oil, water, cracks, burnt or worn places.
- 12) Inspect welding cable lug for proper fixing
- 13) Ensure fire blanket and fire extinguisher with cutting set.

Emergency / Emergency Shut OFF:

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

1. JSA as enclosed below

Job Safety Analysis:

Job Safety Analysis	Job: Inspection of Welding cables & Cutting set	Date:28.2.2018	Analysis by: Section Engineer	Reviewed by: Head	Section
Title of employee doing job: Technician	Supervisor: Section Engineer	Department: Mechanical	Section: Cement Plant	Approved by: Mechanical	HOD

Required/recommended PPE: Safety helmet, Safety shoe, & Safety belt, goggles

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action	
Cutting set & welding cable .	Slip / Fall	Use proper Trolley	Failure of Trolley	Use proper Trolley Deploy trained manpower.	