


Issue No.

DALMIA CEMENT (B) LIMITED – ARIYALUR MECHANICAL SOP



Issued By: MR Approved By: HOD MECHANICAL

ACCUMULATOR REPLACEMENT WORK

Scope : This SOP is applicable to Safe working for Accumulator maintenance

Responsibility: Section Engineer.

Accountability : Section Head - Mills

Rev. No:02

PPE:

1. Safety helmet

- 2. Safety shoe
- 3. Dust Mask,
- 4. Gloves.
 - Cotton knitted
 - Leather
- 5. Safety belt
- 6. Goggles
- 7. Welding Shield

Tools:

- 1. 01T chain block-2nos
- 2. Nylon belt slings- 1Nos.
- 3. Grinding machine
- 4. Ring and fix Spanner set

Auxiliaries

- 1. Welding Set
- **2.** Cutting Set

Hazards:

Risks associated

Mitigating Measures

Body injury

1. Safe and tested tools and tackles

2. on job training

Training needs:

- 1. Emergency preparedness
- 2. On job training
- 3. Assembly procedure

LOTO required for:



DALMIA CEMENT (B) LIMITED – ARIYALUR MECHANICAL SOP



Issue No.	Rev. No:02	Effective Date: 17/10/2017	SOP/MEC/101		
Issued By: MR		Approved By: HOD MECHANICAL			

ACCUMULATOR REPLACEMENT WORK

- 1. Tension hydraulic system
- 2. Mill main drive.

Procedure:

- 1. Make the tension pressure and lift pressure to zero.
- 2. Take electrical shutdown permit of roller hydraulic, with LOTO system.
- 3. The Permit Paper should be with the person who is responsible for the job.
- 4. Trained Worker will be engaged for working with related PPE's.
- 5. Take Height work permit and hot work permit to perform the job.
- 6. Use certified chain block to hold the accumulator.
- 7. Cut the old support of the accumulator holding clamp
- 8. Loosen the bolt and remove the accumulator
- 9. Change the damaged accumulator by new one which is already in spares for emergency situation.
- 10. After changing the accumulator, tighten the bolt.
- 11. Fill the nitrogen gas in bladder and require pressure to set
- 12. Weld the new support of the accumulator holding clamp
- 13. Remove the Chain block.
- 14. Get the line clearance and informed to CCR person.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:



DALMIA CEMENT (B) LIMITED – ARIYALUR MECHANICAL SOP



Section

Reviewed by:

Issue No. Rev. No:02 Effective Date: 17/10/2017 SOP/MEC/101
Issued By: MR Approved By: HOD MECHANICAL

ACCUMULATOR REPLACEMENT WORK

Date: 0.09.12

Analysis by;

1. Refer Line clearance/permit in mechanical department.

Job: Accumulator

2. JSA is enclosed below.

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis

Job Galety Allalysis	replacement	Date. 0.09.12	Section Engineer	Head Approved by: HOD	
Title of employee doing job: Section Engineer	Supervisor: Section Head, Out Sourcing Supply Supervisor	Department: Mechanical	Section: Mills		
eq'd/recommended PPE: He	elmet, Shoe, Nose mask,	Cotton Gloves, Leather glo	ves, Ear plug, Safety	belt, Goggles, Shield	
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action	
Put on PP	Exposure to fumes due to welding operation	Wear Goggles	Damaged goggl	Periodic replacement, Watch person should ensure	
Chain Block lifting	Leg and hand injury	Use proper tools and tackles with certification	Chain block may slip from its lifting position	Check the condition of lifting equipments. 1. Lifting Belts 2. Chain block Periodical replacement is recommended for belts and ropes. Periodical servicing required for Chain blocks.	
Chain Block fixing	Body injury	Use proper PPE (safety belt)	Safety belt failure	Check the condition of PPE Periodical replacement is recommended for belts	
Accumulator flange bolt loosening/tightening	Hand injury	Use proper tools and tackles with certification	Spanner slip /Broken	Check the condition of spanner	
Accumulator holding clamp cutting	Body injury	Use proper cutting set with flash back arrester	Hose pipe damage	Check the condition of hose pipe. Periodical replacement is recommended	



DALMIA CEMENT (B) LIMITED – ARIYALUR MECHANICAL SOP



Issue No.Rev. No:02Effective Date: 17/10/2017SOP/MEC/101Issued By: MRApproved By: HOD MECHANICAL

Grinding the Accumulator holding clamp positioning area	Eye and body injury	1.Use proper guard/locking and tested grinding machine 2.Ensure life of the grinding wheel	.Wheel may slip out from the machine 2.wheel broken	1. To cross check the tightness of wheel 2.check the expiry date of the grinding wheels.
Spare accumulator Replacement	Hand injury	Use proper tools and tackles with certification	Chain block may slip from its lifting position	Check the condition of lifting equipments. 1. Lifting Belts 2. Chain block Periodical replacement is recommended for belts and ropes. Periodical servicing required for Chain blocks.
Welding operation	Hand and Eye injury	Use proper leather hand gloves and welding shield	Damage the welding shield glass and hand glove	Cross check the Periodical replacement of PPE

SL No	Activity		Tag / Name of the Equipment Isolation Type					
			Electrical Energy			Other Energy		
16	Accumulator replacement	Name and Tag for the Equipment	561MD2 / Mill Main Motor	561HP1 / Tension Hydraulic PUMP				