



Issue No. 01 Rev. No: 03 Effective Date: 20.04.2018 SOP/MECH/41

Issued By: M.R Approved By: HOD-Mechanical.

BELT REPLACEMENT

SOP

Scope : This SOP is applicable to Safe working for BELT REPLACEMENT

Responsibility : Section Engineer – Mech Accountability : Section Engineer – Mech

PPE:

1. Helmet,

2. Safety shoe,

3. Hand Gloves

4. Safety goggles.

5. Nose mask.

Tools:

- 1. Chain block 3nos
- 2. Wire rope sling 6nos
- 3. D shackle 4nos.
- 4. Buffing machine
- 5. Hot joint machine
- 6. Pull lift
- 7. Splicing pincer
- 8. Hot air blower
- 9. Mechanical clamps 3sets
- 10. Wire brush

Hazards:

Risks associated Mitigating Measures

Body injury Safe and health tools and tackles Cut injury Safe and health tools and tackles

Training needs:

- 1. Emergency preparedness
- 2. Pneumatic wrench
- 3. Dismantling & Assembly procedure





Issue No. 01	Rev. No: 03	SOP/MECH/41					
Issued By: M.R	Approved By: HOD-Mechanical.						
BELT REPLACEMENT							

Procedure:

- 1. Use Proper PPE & tools
- 2. Take work permit from safety dept as per the work condition.
- 3. Check the tools working condition before start up the job.
- 4. Make the one side splicing of belt. (if required)
- 5. Take the position of belt roll on top of the conveyor with proper direction of joint.
- 6. Take the LOTO & after that Clamp the new belt with old belt.
- 7. Clear the LOTO of belt conveyor and take local operation with mushroom lock ,By On Off take the position of the belt at joint location
- 8 . Take the LOTO of belt conveyor and lift take up with required length of belt With help of clamp lock the belt both carrying and return side
- 9. Belt joining position area idler and frame has to be remove
- 10. According to the belt grade/temperature/material handling to choose the belt joint type

IF COLD JOINT - PROCEDURE

- According to belt width splicing to be done
- Clean, Grinding the belt
- Over lap the both splicing end and check it
- After remove the over lap, Apply the belt joint solution for entire width
- After 10-15 min to check dryness the belt joint solution
- Over lap the belt and slow hammering has to be done





Issue No. 01	Rev. No: 03	SOP/MECH/41				
Issued By: M.R		•	Approved By: HOD-Med	hanical.		
BELT REPLACEMENT						

• After 3 hrs curing time to remove the belt clamp at both carrying and return side

IF HOT JOINT - PRECEDURE

- UHR Belt joint both the end to be positioned and clamped
- Both the end splicing has to be done like that 250mm long in 3 step and In both of the end top and bottom 30mm long channel splicing has to be done. Grinding has to be done
- After splicing both end with steps has to be overlapped with 10mm
- After overlap , both splicing end has to be locked,
- Splicing area has to be cleaned with petrol.
- UHR Rubber solution has to be applied 2 coat on splicing area. Blower has to be applied
- UHR 710 T60 Skin compound has to be applied on splicing area.
- C2 for cover compound has to be applied on end channel.
- Both the end matching has to be done.
- Hot vulcanizing hydraulic machine has to be fixed.
- Switch on power and temp 40deg, oil pressure 100bar heating has to be done.
- Oil 180bar pressure, 150 deg temp has to be reached.
- Oil 300bar pressure, 155 deg temperature has to maintained in one hour.
- After one hour heating , stop the heating and maintain the pressure 300 bar
- Cooling has to be done and temperature has to be reached below 55deg.
- Hot vulcanizing hydraulic machine has to be dismantled.





Issue No. 01	Rev. No: 03	Effe	ctive Date: 20.04.2018	SOP/MECH/41		
Issued By: M.R			Approved By: HOD-Mech	anical.		
BELT REPLACEMENT						

- Belt joint has to be checked for operation
 - 11. Fix all the idler and frame.
 - 12. Down the take up and required length
 - 13. Remove the all tools and tackles from belt
 - 14. Clear the LOTO, take local operation
 - 15. By on- off condition remove the old belt with help of hydra
 - 16. Take the no load trail and adjust the Belt if required
 - 17. Remove the man and tools from work place
 - 18. Close the Work permit and give clearance for operation

Emergency / Emergency Shut OFF:

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

- 1. Refer Line clearance in Process department.
- 2. JSA is enclosed below.

JOB SAFETY ANALYSIS: (JSA)





Issue No. 01 Rev. No: 03 Effective Date: 20.04.2018 SOP/MECH/41

Issued By: M.R Approved By: HOD-Mechanical.

BELT REPLACEMENT

			T		
Job Safety Analysis	Job:Belt replacement	Date: 01/09/2014	Analysis by: Section Engineer	Analysis by: Section	
Title of employee doing job: Site incharge	Supervisor: Section Engineer	Department: Mech	Section: LS CRUSHER	Approved by: HOD-Mechanical.	
Req'd/recommend	ded PPE: Safety Helme	et, Safety shoe, Hand Gloves,	, Safety goggles. Nose mask.		
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action	
Make the one side splicing	Body injury	Use proper tools for splicing the belt	Pull lift may slip and hit hands while splicing. pincher may slip / cut during load	Check the condition of the Pull lift / pincher and Dshackle	
Rolling the new belt	Hand injury	Use trained persons to roll the belt	Fingers may caught inbetween the belt	Create awareness for persons	
Lifting the belt to top of the old belt	Body injury	Use certified lifting tools / cranes only.	Lifting sling may damage	Check the condition of the sling, chainblock / crane load and swing angle and certification to use.	
Take the position of belt roll on top of the conveyor with proper direction of joint.	Body injury	Use recommended tools only to avoid unsafe operation .	Hand or finger may caught in between	Check the condition of handgloves	





Issue No. 01 Rev. No: 03 Effective Date: 20.04.2018 SOP/MECH/41

Issued By: M.R Approved By: HOD-Mechanical.

BELT REPLACEMENT

Clamp the new belt with old belt	Body injury	Use proper regulators and flashback arrestors only to Hose burn, torch melting ensure safe operation .		Check the condition of regulators and flashback arrestors
	Burn injury	Use proper handgloves Hand gloves may be in damage condition		Check the condition of handgloves
Positioning the belt	Hand injury or cut	Don't touch the belt while on/off time Hand or fingure may caught in between		Operating person should ensure nobody was near to the belt
Remove the old belt	Cut injury	Use good knife to cut the belt.	Knife may be in damage condition	Check the condition of Knife
			It may scratch/ cut the fingure of the handling person/ other persons nearby	
Take the Line clearence	Body injury	Use work permit system.	Drive may run	Check the lockout & tagout system
Lifting the take up	Hand injury	Use good Chainblocks/slings/ Dshakkle to lift the takeup.	Chainblocks/slings/Dshak kle may be in damage condition	Check the condition of lifting tools
	Fall down	Use proper mechanical safety belt.	Persons may slip down from the platform	Check safety belt and its condition
Remove the frame and idlers from joint area	Body injury	Use proper spanners only to avoid slip / shear of bolt and nut during removing.	load	Check the condition of the bolt / nut and spanner
Other end Splicing the belt	Body injury	Use proper tools for splicing the belt	Pull lift may slip and hit hands while splicing. pincher may slip / cut	Check the condition of the Pull lift / pincher and Dshakkle
Clean, Grind & clean & join the	Clean, Grind & Body injury machines only to avoid bit		Buffing disc may cut and hit hands while cleaning.	Check the condition of the buffing wheel / handle.
belt joint	Eye injury & Dust	Use safety goggles, nosemask and earplug	PPE may be damage condition	Check the condition of PPE
Cold joint	Hand injury	Use certified rollers to ensure safe operation	Hand or fingure may caught in between	Operating person should ensure nobody was near to rolling area





Issue No. 01 Rev. No: 03 Effective Date: 20.04.2018 SOP/MECH/41
Issued By: M.R Approved By: HOD-Mechanical.

BELT REPLACEMENT

	Hand injury			Check the condition of	
	joint Electric shok Burn injury Body injury Body injury Body injury Jose proper spanners only to avoid slip / shear of bolt and nut during fixing. Jose proper spanners only to avoid slip / shear of bolt and nut during opening. Jose proper spanners only to avoid slip / shear of bolt and nut during opening. Jose proper spanners only to avoid slip / shear of bolt and nut during opening. Jose good Chainblock slings/ Dshakkle to down the takeup. Lise proper mechanical persons of the proper spanners only to avoid slip / shear of bolt and nut during opening. Chainblock slings/ Dshakkle to down the takeup.	damage condition	lifting clamps		
		Use certified hot		Check the condition of	
Hot joint	Electric shok		Powercable damage	the cable and	
	Electric shok Burn injury Burn injury Burn injury Body injury The Bod		certification to use.		
	Rurn injury	l lse proper handgloves	Hand gloves may be in	Check the condition of	
Burn injury Ose proper handgiov	Ose proper nanagioves	damage condition	handgloves		
		Use proper spanners only	Spanners may slip and hit	Check the condition of	
Fix the frame and	Rody injury 1		nands while opening.	the holt / nut and	
idlers of joint area		•	poit may shear / cut during	spanner	
		and national managements	load spa		
	Body injury	Use proper spanners only	Spanners may slip and hit	Check the condition of	
Removing the			nands while opening.	the holt / nut and	
clamp	clamn I , , , I		poit may shear / cut during	spanner	
		<u> </u>	load	'	
		_ ~	Chainblocks/slings/Dshak		
Releasing the	Hand injury		kle may be in damage	Check the condition of	
take up	, ,		condition	lifting tools	
		•			
	Fall down		Persons may slip down	Check safety belt and	
		safety belt.	from the platform	its condition	

SL	I ACTIVITY I I			Isolation Matrix for Utility & General Equipment.					
No	_			Isolation Type					
				Electrical Energy Other Energy					
6	Conveyor Belt Replacement	Name and Tag for the Equipment		Drive for the Equipment	Feeding Equipment.	Discharge equipment		Belt locking at both sides of the joint	