

## DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR SAFETY DEPARTMENT MANUAL



Issue No. 01 Rev. No: 00 Effective Date: 01.11.2010 WI-20(PI-14; AM-7)

Issued By: M.R Approved By: HOD -SAFETY

**WORK INSTRIUCTION FOR SAFETY PRECAUTIONS AT KILN** 

## **1.0 WORKING WITH THE ROTARY KILN AND ITS AUXILIARIES:**

## 1.1 DON'Ts

- 1.1.1 Do not open manhole covers of the hoppers/cyclones unless you ensure that they are Completely empty. The fine material could be very hot and they could cause burn injuries.
- 1.1.1 Do not open the pre heater cyclone doors when the Kiln is running.
- 1.1.2 Do not stand near the cyclone inspection hole. If it is open, when the pre heater fan is running on high speed, the suction in the cyclone could draw you in.
- 1.1.3 Do not attempt to remove the cyclone jam till you ensure that nobody is on Burner's platform and near to the clinker breaker.
- 1.1.4 Do not allow unauthorized persons on Kiln platform during the kiln light up. There could be sudden back fire which can cause serious burn injuries.
- 1.1.5 Do not attempt to clean the supporting rollers of Kiln with the kiln in operation and wearing loose clothing.
- 1.1.6 Do not some anywhere in or near the coal mill and accessories. Coal hoppers, coal silos, bag filters, kiln hood etc. The inflammable gases like CO may cause an explosion hazard.
- 1.1.7 Do not enter the Kiln unless you ensure that no one will start the kiln drive. Take line clearance.
- 1.1.8 Do not enter the kiln until you ensure adequate draught is maintained through out. This is very much essential in case of common chimney.
- 1.1.9 Do not enter without proper protection to your head.
- 1.1.10 Do not use a hand-lamp other than 24V.
- 1.1.11 Do not allow unauthorized persons inside the kiln.



## DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR SAFETY DEPARTMENT MANUAL



Issue No. 01 Rev. No: 00 Effective Date: 01.11.2010 WI-20(PI-14; AM-7)

Issued By: M.R Approved By: HOD -SAFETY

WORK INSTRIUCTION FOR SAFETY PRECAUTIONS AT KILN

- 1.1.12 Do not start the kiln rotation until you ensure that no one is inside the kiln or on the top of the kiln.
- 1.1.13 Do not Blast the set clinker in cyclones with detonators, Major accidents have caused due to blasting in cyclone.
- 1.1 <u>DOs</u>
- 1.1.1 Before lighting the kiln ensure that no one is working inside the raw mill as the smoke may enter inside the mill resulting in severe injuries.
- 1.1.2 Before entering the coal silos, kiln, raw mill and cyclones and hoppers, check for the toxic and poisonous & flammable gases.
- 1.1.3 Before removing the jam ensure that you are wearing adequate personal protection equipments.
- 1.1.4 Ensure that unauthorized persons are cleared off from the cyclone floors.
- 1.1.5 Ensure that during the removal of cyclone jams one of the fans in pre heater and exhaust should be kept running to provide adequate draught.
- 1.1.6 Ensure that while cleaning revolving part of the kiln such as Rollers etc., you are wearing tight fitting clothing, also do not wear full sleeve shirts.
- 1.1.7 Ensure that kiln drive and PH Fan drives are locked and have the keys with you before entering the Kiln.
- 1.1.8 Always use a proper tool for repairs of rollers and such other parts of kilns.