DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MEC/056

Issued By: M.R Approved By: HOD Mechanical

VIBRATING SCREEN INLET & OUTLET EXPANSION JOINT REPLACEMENT.

Scope: VIBRATING SCREEN EXPANSION JOINT REPLACEMENT

Responsibility: Section Engineer

Accountability: Mechanical-Section Incharge

PPE:

1. Safety helmet,

- 2. Safety shoe,
- 3. Mask.
- 4. Gloves Cotton knitted
- 5. Ear Plug
- 6. Safety belt
- 7. Goggles

TOOLS:

- 1. Box spanner set.
- 2. Ring spanner set.
- 3. Grease gun.
- 4. Local stop key.

Hazard Analysis:

<u>Risks associated:</u> <u>Mitigating Measures</u>

Dust emission Use Nose Make, Goggles & Ear Plug.

Vibrating screen inlet & outlet expansion joint replacement

- 1) Take the line clearance for Vibrating screen and keep in out of service from control room.
- 2) The line clearance paper should be with the person who is working in the site.
- 3) Trained Worker should be engaged for working with related PPE"s.
- 4) Use Certified Tools & Tackles for the job
- 5) Remove the inlet/outlet expansion joint cloth clamp with bolts.

DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MEC/056

Issued By: M.R Approved By: HOD Mechanical

VIBRATING SCREEN INLET & OUTLET EXPANSION JOINT REPLACEMENT.

- 6) Fix the new expansion joint cloth with clamping arrangement.
- 7) Fix the clamp bolts.
- 8) Clear the Line clearance and take trial.

Emergency / Emergency Shut OFF:

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below

3.

SL No	Activity		Isolation Matrix for Utility & General Equipment. Isolation Type Electrical Energy Other Energy			ment.	
1	Vibrating screen maintena nce work	Name and Tag for the Equipm ent	Vibrating screen	Elevator main drive	Elevator Auxi drive		



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issued By: M.R Approved By: HOD Mechanical

VIBRATING SCREEN INLET & OUTLET EXPANSION JOINT REPLACEMENT.

Job Safety Analysis:

Job Safety Analysis	Job: Vibrating Screen Expansion joint replacement	Date: 01/09/2014	Analysis by: Section Engineer	Reviewed by: Section Incharge
Title of employee doing job: Fitter	Supervisor: Section Engineer (Mech.)	Department: Mechanical	Section: Packing Plant	Approved by: HOD Mech.

Req'd /recommended PPE:

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Remove the screw clamp	Hand injury	Use proper tools Lifting tools	Tools / clamp may slip	Ensure proper tools & tackles in usage
Tightening the clamp	Finger injury	Use proper tools Lifting tools	Tools / clamp may slip	Ensure proper tools & tackles in usage



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01	Rev. No: 02	Effective Date: 17.10.2017	SOP/MEC/056
--------------	-------------	-----------------------------------	-------------

Issued By: M.R Approved By: HOD Mechanical VIBRATING SCREEN INLET & OUTLET EXPANSION JOINT REPLACEMENT.