

# DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



INSTRUMENTATION DEPARTMENT

Issue No. 01 | Rev. No: 01 | Effective Date: 01.01.2016 | WI-8 (SP-8; AM-7)

Issued By: M.R Approved By: HOD-INSTRUMENTATION

CALIBRATION PROCEDURE OF WEIGH FEEDER

The Instrument engineer takes action as follows, for calibration:

- 1.1 STATIC CALIBRATION PROCEDURE:
- 1.1.1 Weigh feeder must be selected in Volumetric mode.
- 1.1.2 Belt should be Empty condition
- 1.1.3 TARE ADJUSTMENTS:
- 1.1.3.1 Start Weigh Feeder at full speed without weight. Set point must be 100% (P value in TPH)
- 1.1.3.2 IF TPH indication will appear "zero", no need to TARE adjustment
- 1.1.3.3 IF TPH indication will not appear "zero"
- 1.1.3.4 Go to calibration mode.
- 1.1.3.5 Press Tare
- 1.1.3.6 TPH rate indication becomes zero. If not zero, repeat step 1 to 5.
- 1.1.4 SPAN ADJUSTMENT:
- 1.1.4.1 Start Weigh Feeder at full speed; apply known weight (as per calibration chart). TPH indication should indicate the reading corresponding to the weight applied as per chart. If not, adjust the span.
- 1.1.4.2 Run belt empty.
- 1.1.4.3 Apply the known test weights on both sides of load cell freely
- 1.1.4.4 IF TPH indication will appear corresponding to the weights applied, no need to span adjustment



## DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



#### **INSTRUMENTATION DEPARTMENT**

Issue No. 01 Rev. No: 01 Effective Date: 01.01.2016 W	WI-8 (SP-8; AM-7)
---	-------------------

Issued By: M.R Approved By: HOD-INSTRUMENTATION

### CALIBRATION PROCEDURE OF WEIGH FEEDER

- 1.1.4.5 IF TPH indication not match with applied weights
- 1.1.4.6 Adjust the span in D02

TPH=(TEST WEIGHT/WEIGHING ZONE)\*BELTSPEED\*3.6.

- 1.1.4.7 TPH indication will appear corresponding to the weights applied.
- 1.1.4.8 IF not, repeat from step 1 to 6
- 1.1.4.9 Record the observations in the Instrument calibration format F-1/WI-8(SP-8; AM-7)

#### **2.0 CONNECTED DOCUMENTS:**

F-1/WI-8(SP-8; AM-7)

Calibration of Weigh feeder.

LIMESTONE WEIGH FEEDER-1	CAPACITY 600 TPH
TEST WEIGHTS in Kg	ТРН
20.0	45.9
30.0	68.9
40.0	91.9
10.0	71.7
SWEETNER WEIGH FEEDER	CAPACITY 600 TPH
TEST WEIGHTS in Kg	ТРН
20.0	45.9
30.0	68.9
40.0	91.9
LIME STONE WEIGH FEEDER-2	CAPACITY 500 TPH
TEST WEIGHTS in Kg	TPH
20.0	12.1
30.0	18.1
40.0	91.9
	,
FIRECLAY WEIGH FEEDER	CAPACITY 50 TPH



## DALMIA CEMENT (B) LIMITED – CEMENT PLANT **ARIYALUR**



#### **INSTRUMENTATION DEPARTMENT**

Issue No. 01	<b>Rev. No: 01</b>	<b>Effective Date: 01.01.2016</b>	WI-8 (SP-8; AM-7)
<b>Issued By: M.R</b>		Approved By: HOD-INSTRUM	IENTATION

## CALIBRATION PROCEDURE OF WEIGH FEEDER

TEST WEIGHTS in Kg	ТРН
20.0	20.2
30.0	30.2
COAL WEIGH FEEDER-1	CAPACITY 60 TPH
TEST WEIGHTS in Kg	ТРН
10.0	10.08
20.0	20.16
30.0	30.24
COAL WEIGH FEEDER-2	CAPACITY 60 TPH
TEST WEIGHTS in Kg	ТРН
10.0	10.08
20.0	20.16
30.0	30.24
CLINKER APRON FEEDER	CAPACITY 400 TPH
TECT WEIGHTS :- V-	ТРН
TEST WEIGHTS in Kg	
20.0	10.0
30.0	15.0
40.0	20.0
WET FLY ASH WEIGH FEEDER	CAPACITY 150 TPH
TEST WEIGHTS in Kg	TPH
20.0	30.2
30.0	45.4
40.0	60.5
10.0	00.5
GYPSUM WEIGH FEEDER	CAPACITY 40 TPH
TEST WEIGHTS in Kg	TPH
20.0	4.9
30.0	7.3
40.0	9.8
TU.U	7.0



## DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



#### **INSTRUMENTATION DEPARTMENT**

Issue No. 01	<b>Rev. No: 01</b>	<b>Effective Date: 01.01.2016</b>	WI-8 (SP-8; AM-7)
--------------	--------------------	-----------------------------------	-------------------

Issued By: M.R Approved By: HOD-INSTRUMENTATION

## CALIBRATION PROCEDURE OF WEIGH FEEDER

TEST WEIGHTS in Kg	TPH
15.0	7.75
10.0	5.2
5.0	2.5