

DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL

Issue No. 02 | Rev. No: 00 | Effective Date: 01.11.2019 | SOP/MEC/186

Issued By: M.R Approved By: HOD-Mechanical

SOP - REPLACEMENT OF ROTARY AIR LOCK

SOP FOR ROTARY AIR LOCK DISC WELDING

Scope : This SOP is applicable to Safe working of RAL disc welding

Responsibility : Section Engineer mech
Accountability : Section Incharge mech

PPE:

Safety harness(Full body)

- 2. Safety helmet,
- 3. Safety shoe,
- 4. Nose Mask,
- 5. Hand gloves
- 6. Safety goggles

TOOLS:

- 1. spanner set
- 2. chain blocks
- 3. Crowbar
- 4. Slings
- 5. D-shackles
- 6. Hydraulic jack

Hazard Analysis:

Risks associated: Mitigating Measures

Fall from height, Use of safety harness

Hand or Leg slipping in to the rotary vanes

Locking the movement of rotor

Fall of chain Block

Use certified chain block as required

Fall of tools, Carry the tools in tool box/bag

Contact with hot body

Use of hand gloves/apron

Procedure:

Dalmia BHARAT CEMENT

DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL

Issue No. 02 | Rev. No: 00 | Effective Date: 01.11.2019 | SOP/MEC/186

Issued By: M.R Approved By: HOD-Mechanical

SOP - REPLACEMENT OF ROTARY AIR LOCK

- 1. Stop the RAL and take the work permit as per LOTO for all the feed & Discharge equipment.
- 2. The line clearance paper should be with the authorized person who is working in the site. In case of man entering inside the hopper/chute take the confined area work permit from the relevant department and allow the persons to work
- 3. Use PPE's while working.
- 4. Open the main man holes.
- 5. Remove the coating/material in the RAL
- 6. Lock the RAL by fixing the rod on vanes plate in hole of casing area
- 7. Remove the small door of rotary air lock side disc area
- 8. By rotating the motor cooling fan RAL to be positioned
- 9. After positioning the RAL the worn out portion of side disc can be weld
- 10. Direct earth to be connected
- 11. By using the certified welder & welding machine the job can be start
- 12. Side disc can be welded with suitable welding electrode
- 13. After the welding the area to be grinded with grinding machine
- 14. By rotation of RAL free movement to be ensured
- 15. Release the locking bolt and close the all door.
- 16. Clear the LOTO and take the trail run, check the direction and record the amps
- 17. If it found 0k then inform to the CCR.

Emergency Shut- off:

In such cases, the rotary air lock must be placed on floor and chain block should be freed from load. All tools and tackles should not be in the workstation, to be placed in the tool box/ floor in a systematic manner in order to avoid fall of the same.

Emergency / Emergency Shut OFF:

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure: Job safety analysis.

JOB SAFETY ANALYSIS: (JSA)



DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/186

Issued By: M.R Approved By: HOD-Mechanical

SOP - REPLACEMENT OF ROTARY AIR LOCK

Job Safety	Job: RAL Disc	Date:21.04.2020	Analysis by: Section	Reviewed by:		
Analysis	welding		Engineer	Section Head		
Title of employee doing job: Section Incharge Supervisor: Section Sr.Engineer (Mech.)		Department: Mechanical	Section: VRM'S	Approved by: HOD Mechanical		

Req'd /recommended PPE:

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action		
Rotate RAL in reverse/forward direction with wet/lump material	Minor Injury	Ensure the inspection door & coupling guard is in closed condition	To remove choke work men may open the inspection door & operate the RAL	Engage trained workmen. Continuous		
			Contact of body parts with rotating equipment.	supervision of site engineer is required		
Open RAL side door and remove	Injury / fracture	Ensure LOTO procedure	Slippage of tools.	Engage trained workmen.		
accumulated material.		& rotor is locked at blades to casing to avoid movement		Use PPE		
Rotate in reverse /forward direction in local mode.	Minor Injury	Ensure the inspection door is in closed condition	To remove choke work men may open the inspection door & operate the RAL	Engage trained workmen.		
			Contact of body parts with rotating equipment.	supervision of site engineer is required		



DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/186

Issued By: M.R Approved By: HOD-Mechanical

SOP - REPLACEMENT OF ROTARY AIR LOCK

Isolation Matrix:

15 Mill Feed RAL		Name an Tag for th Equipmer	е	561MD2 / Mill Main Motor	561SR1 / Clasifier	561FN1 / Mill Fan	561AD2/ Axilary drive Chain not to be connected	Rollers Position Landed & Pressure Zero at Pannel	561DV1 / Diveting Gate Air Valve.
	Mill Feed RAL	Name an Tag for th Equipmen	е	561RA1 / Mill feed RAL	561FN4 / Booster fan	561SD2 / Hot Air Shut-off Damper(In closed condition only)			
		Name and Tag for the Equipment	е	K21 RA4 / DFA Feed RAL	531BC2 / mill feed Belt Conveyor.				