

DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM MECH DEPARTMENT



Issue No. 01 Rev. No: 00 Effective Date: 01.03.2016 SOP/MECH/60

Issued By: S.P Approved By: HOD (MECH)

SOP FOR CRUSHER V- BELT CHANGING WORK

Scope/Purpose: This SOP is applicable to Safe working for V- belt replacement

Responsibility : Engineer – Mech

Accountability : Dept.HOD / Site Engineer

PPE:

1. Safety helmet,

2. Safety shoes,

3. Safety Harness

4. Goggles

Tools:

1. Electrically Operated Trolley Crane

2. Wire rope slings

3. Chain pulley block

4. Spanners of various sizes

5. Hydraulic jack

6. Hammer

Hazard Analysis:

Risks associated Mitigating Measures

Fall of material Use trained workmen and tested tools and tackles Burstage of hydraulic hose Use trained workmen and tested tools and tackles

Training needs:

- 1. Usage of tools & PPE
- 2. Heavy lifting
- 3. Hydraulic cylinder usage



DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM MECH DEPARTMENT



Issue No. 01 Rev. No: 00 Effective Date: 01.03.2016 SOP/MECH/60

Issued By: S.P Approved By: HOD (MECH)

SOP FOR CRUSHER V- BELT CHANGING WORK

Procedure:

- 1. Use Proper PPE & tools
- 2. Take proper Line clearance of crusher, wobbler and 21NBC1 belt conveyor from concerned dept. as per the work condition.
- 3. Loosen the drive bed of crusher to make v-belt loose.
- 4. Mark the jack shaft housing and lift the jack shaft assembly using chain block.
- 5. Remove the old worn out belt from the drive and driven pulley.
- 6. Insert the new V belt 14 from one end and next 14 from other end.
- 7. Place the new V belt in the pulley groves without any twists.
- 8. Tighten the housing bolts of jack shaft after positioning in the marked place.
- 9. Tighten the total drive bed assembly for proper tensioning of V belt.
- 10. Check the tension as per required standards

Emergency / Emergency Shut OFF:

1. If cut or fall injury is there, First aid should be given and Safety department to be informed. Call Emergency number 222/516/523/9865177444/9865195111.

Records/Annexure:

1. Hazard identification sheet is enclosed below.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT DALMIAPURAM MECH DEPARTMENT



Issue No. 01 Rev. No: 00 Effective Date: 01.03.2016 SOP/MECH/60

Issued By: S.P Approved By: HOD (MECH)

SOP FOR CRUSHER V- BELT CHANGING WORK

Hazard Identification:

Hazard Identification	Job: crusher V belt replacement	Date:	Analysis by: Mech dept.	Reviewed by: Safety dept.
Title of employee doing job: Company workmen	Supervisor: Section Engineer	Department: Mech	Section: Plant	Approved by: Unit Head
Req'd/recommended PPE: Safety helmet, Safety shoes, Safety belt, & Goggles				
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Tying the wire rope sling to the jack shaft	Untested tools taken for usage/damaged tools/failure of lifting material & exceed SWL	Tested tools to be mandatory use at site Physical condition of tools to be verified before taken into use by line engineers Proper fixing of lifting tools with considering load carrying capacity.	Fall of material	1. Test certificates of tools to be ensured 2. Validity of test certificate to be verified 3. Trained persons to be engaged
Hydraulic jack usage for adjusting the housing position	Failure of hyd. Jack/hose burstage/slipping of jack from position	Check condition of jack/ensure hose healthiness/tie jack with rigid support before giving load	Oil burstage/jack slip and fall	Hyd. jack inspection due date to be verified. Ensure workmen not very close to the working area during jack load condition