

Issue No. 01

## DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION DEPARTMENT



Rev. No: 00 Effective Date: 01.11.2010 WI-11 (SP-8; AM-7)

Issued By: M.R Approved By: HOD-INSTRUMENTATION

**CALIBRATION PROCEDURE OF WEIGH BRIDGE** 

The Instrument engineer takes action as follows, for calibration:

- 1.1 TARE CALIBRATION:
- 1.1.1 Ensure that the weigh bridge platform is clean.
- 1.1.2 When platform is empty output indication should show 00.00 tones.
- 1.1.3 If not press tare key reading will show 00.00
- 1.2 SPAN CALIBRATION
- 1.2.1 Place a standard 5 ton weight on the platform.
- 1.2.2 Press Cal button on the Indicator it would ask for the password.
- 1.2.3 Enter the password, Indicator would display the previous calibrated value.
- 1.2.4 Enter the applied weight value (on the platform) and press enter.
- 1.2.5 Applied weight value appears on the indicator.
- 1.2.6 Repeat the above procedure to obtain reliable and stable values.
- 1.2.7 Record the observations in the instrument calibration format F-1/WI-11(SP-8; AM-7)



## DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



## **INSTRUMENTATION DEPARTMENT**

Issue No. 01	<b>Rev. No: 00</b>	Effective Date: 01.11.2010	WI-11 (	SP-8; AM-7)	)
10040 1101 0 1	1101110100	Ziicceive Butei o IiI I i 2010	, ,,, , , , , , , , , , , , , , , , ,	01 0,111.1	,

Issued By: M.R Approved By: HOD-INSTRUMENTATION

CALIBRATION PROCEDURE OF WEIGH BRIDGE

## 2.0 CONNECTED DOCUMENTS:

F-1/WI-11(SP-8; AM-7)	Calibration of Weigh Bridge		
WEIGHBRIDGE-1	CAPACITY 100.0 Ton		
TEST WEIGHTS (TON)	TON (DISPLAY)		
1.0	1.0		
3.0	3.0		
5.0	5.0		

WEIGHBRIDGE-2	CAPACITY 100.0 Ton		
EST WEIGHTS (TON)	TON (DISPLAY)		
1.0	1.0		
3.0	3.0		
5.0	5.0		