# **Dalmia** BHARAT CEMENT

## **DALMIA CEMENT (B) LIMITED - Ariyalur**

#### **Mechanical SOP**

Issue No:02 Rev No:00 Effective Date: 01/11/2019 SOP/MEC/043

ISSUED BY: (MR) APPROVED BY: HOD Mechanical.

#### SOP FOR CLEARING ROTARY AIR LOCK

**Scope**: This SOP is applicable for Safe working of Mill Feed rotary air lock jam clearing Work

Responsibility: Section Engineer.

Accountability: Section Head

PPE:

1. Safety helmet

- 2. Safety shoe
- 3. Dust mask
- 4. Cotton Knitted hand Gloves
- 5. Ear Plug
- 6. Full Body harness
- 7. Goggles

Tools:

- 1. Spanner set-1 no
- 2. 10 Ton Jack -1no

Hazards:

Risks associated Mitigating Measures

Hot gas and Fine Dust Wear Goggles and Dust Mask

**Training needs:** 

1. Emergency preparedness

2. On job training

### **Isolation Required:**

Rotary air lock

### **Procedure**

- 1. Ask CCR people to keep RAL in local mode.
- 2. Rotate RAL in reverse/forward direction wherever it trips with wet/lump material.
- 3. If it does not rotate, take LOTO permit.
- 4. Lock the rotor blade with locking bolt (locking bolts are in casing).
- 5. Open RAL side door and remove accumulated material.
- 6. Don't send persons inside RAL casing.
- 7. After removing the jam material, check the RAL blades condition and gap.
- 8. Clear LOTO permit and rotate in reverse direction in local mode.
- 9. Check the current at empty load.
- 10. When RAL is free, close the man whole door and ask the CCR people to take it in sequence.

# **Dalmia** BHARAT CEMENT

## **DALMIA CEMENT (B) LIMITED - Ariyalur**

#### **Mechanical SOP**

Issue No:02 Rev No:00 Effective Date: 01/11/2019 SOP/MEC/043

ISSUED BY: (MR) APPROVED BY: HOD Mechanical.

## **SOP FOR CLEARING ROTARY AIR LOCK**

## **Emergency / Emergency Shut OFF:**

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

## **Records/Annexure:**

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below.

### **Job Safety Analysis:**

Job Safety	Job: RAL Jam	Date:01/09/2014	Analysis by: Section	Reviewed by:
Analysis	Clearing		Engineer	Section Head
Title of employee doing job: <b>Fitter</b>	Supervisor: Section Sr.Engineer (Mech.)	Department:  Mechanical	Section: VRM'S	Approved by: HOD Mechanical

#### Req'd /recommended PPE:

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Rotate RAL in reverse/forward direction wherever it trips with wet/lump material	Minor Injury	Ensure the inspection door & coupling guard is in closed condition	To remove choke work men may open the inspection door & operate the RAL Contact of body parts with rotating equipment.	Engage trained workmen.  Continuous supervision of site engineer is required



## DALMIA CEMENT (B) LIMITED - Ariyalur

## **Mechanical SOP**

Issue No:02 Rev No:00 Effective Date: 01/11/2019 SOP/MEC/043

ISSUED BY: (MR) APPROVED BY: HOD Mechanical.

## **SOP FOR CLEARING ROTARY AIR LOCK**

Open RAL side door and remove accumulated material.	Injury / fracture	Ensure LOTO procedure & rotor is locked at blades to casing to avoid movement	Slippage of tools.	Engage trained workmen. Use PPE
Rotate in reverse /forward direction in local mode.	Minor Injury	Ensure the inspection door is in closed condition	To remove choke work men may open the inspection door & operate the RAL Contact of body parts with rotating equipment.	Engage trained workmen.  Continuous supervision of site engineer is required