

## DALMIA CEMENT (B) LIMITED - ARIYALUR



## **MECHANICAL SOP**

Issue No. 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MEC/063

Issued By: M.R Approved By: HOD Mechanical

S.F. COOLER U-PROFILE REPLACEMENT

## Scope:

This SOP is applicable for S.F. Cooler U-profile replacement safely.

**Responsibility** : Section Engineer – Mech.

Accountability : Section head - Mech.

#### PPE:

- 1. Helmet,
- 2. Safety shoe,
- 3. Goggles
- 4. Gloves.
- 5. Nose mask
- 6. Full body harness

#### Tools:

- 1. Spanner set
- 2. Hammer

## **Hazards:**

#### **Risks associated**

- 1. Body injury
- 2. Leg injury
- 3. Hand injury

## **Mitigating Measures**

- 1. Safe and tested tools and tackles
- 2. On job training



## **DALMIA CEMENT (B) LIMITED - ARIYALUR**



## **MECHANICAL SOP**

Issue No. 01	Rev. No: 02	Effe	ctive Date: 17.10.2017	SOP	/MEC/063

Issued By: M.R Approved By: HOD Mechanical

S.F. COOLER U-PROFILE REPLACEMENT

#### **Isolation matrix:**

SI: No	Activity	Description	Electrical Energy			Other Energy	
	SF Cooler U profile replace ment		Cooler all four drives	Cooler all fans (471FN1 to 471FN7)	(471CC1) Hammer crusher & Cooler water spray pump (471WP1)	Inlet air blasters Compressor air Valve to be Closed & locked	Air in the Header to be released
1		le Tag for the	Primary Air fan 481FN2&3	(461KL1) Kiln main drive	(461AD1) Kiln aux	Hydraulic line pressure to be made zero	
			(431MD1& MD2)Ph bucket elevator	Kiln (481BL1) and pc (451BL1) & Standby blowers	Pre-heater (441FN1) and ESP fan (471FN8)	Cooler water s <sub>i</sub> valve closing aft zero	er line made

# SOP for S.F. Cooler U-profile replacement

- 1. 1. Energy isolation of the equipment to be taken from the concern department as per above matrix.
- 2. Ensure use of PPE & dust mask etc
- 3. Take Confined Area work permit from the safety department and process
- 4. Open the doors of cooler.
- 5. Arrange proper lightening inside the cooler.(24 v)
- 6. Clean the clinker bed of the cooler and put it into the circuit.

# **Dalmia**BHARAT CEMENT

## **DALMIA CEMENT (B) LIMITED - ARIYALUR**



## **MECHANICAL SOP**

Issue No. 01	<b>Rev. No: 02</b>	<b>Effective Date: 17.10.2017</b>		SOP/MEC/063	
Issued By: M.R			Approved By: HOD Mechanical		

S.F. COOLER U-PROFILE REPLACEMENT

- 7. Remove the locking wedges & spring pins from cross bar retainer bracket
- 8. Remove the retainer bracket
- 9. Remove the Cross bars movable & stationary
- 10. Remove the U-profile
- 11. Fix the new U-profile in position
- 12. Fix the new cross bar on the position
- 13. Fix the retainer bracket
- 14. Fix the wedges in position
- 15. Measure the gap between stationary cross bar & U-profile (2 to 6mm)
- 16. Measure the gap between U-profile & ADP plate-2mm
- 17. Drill the locking wedges by hand drilling machine (drill size-8mm)
- 18. Fix the new spring pins of 8mm
- 19. Remove all old item & return back into stores.
- 20. Clear all LC's & Return the work permit.
- 21. Take trail of the cooler & check the cooler in operation.

#### **Emergency / Emergency Shut OFF:**

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

# **Records/Annexure:**

- 1. Refer Line clearance/permit in mech department.
- 2. JSA is enclosed below.

JOB SAFETY ANALYSIS: (JSA)



# **DALMIA CEMENT (B) LIMITED - ARIYALUR**



## **MECHANICAL SOP**

Issue No. 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MEC/063

Issued By: M.R Approved By: HOD Mechanical

# S.F. COOLER U-PROFILE REPLACEMENT

Job Safety Analysis	Job: Cooler "U" profile replacement	Date: 01/9/2014	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job: Section Engineer	Supervisor: Section Head	Department: Mech.	Section: PYRO	Approved by: HOD Mechanical

Req'd/ recommended PPE: Safety helmet, Safety shoe, Gloves, Goggles, Gloves, Nose mask & Full body harness

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action	
Opening of the cooler doors	hand injury	Use proper tools and tackles so that fasteners will not slip	Fasteners may slip and tools may hit to the hand and leg	Ensure Use/working condition of TOOLS AND TACKLES.	
Clean the clinker bed & check the condition	Health injury	Use goggles & nose mask & 24 V lights	Dusty area (Clinkers fines) may leads to suffocation & eye problem	Ensure Use of goggles & nose mask. <mark>Use 24 V lights for working</mark>	
Removing of locking wedges, spring pins & retainer bracket	Leg and hand injury	Use proper tools and tackles for safe removing	Fasteners may slip and tools may hit to the hand and leg.	Ensure Use/working condition of TOOLS AND TACKLES.	
Replacement of U- profile	hand injury	Use hand gloves	Worn out profile sharp edges may injure the fingers	Ensure Use of hand gloves	
Fixing of retainer bracket, locking wedges, spring pins	Leg and hand injury	Use proper tools and tackles for safe fixing of	Fasteners may slip and tools may hit to the hand and leg.	Ensure Use/working condition of TOOLS AND TACKLES.	