DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01	Rev. No: 02	Effective Date:17.10.2017	SOP/MEC/052

Issued By: M.R Approved By: HOD -Mechanical

SOP Thruster replacement

<u>Scope</u>: Replacement of thruster. Responsibility: Section Engineer

Accountability: Mechanical - Section Incharge

PPE:

1. Safety helmet,

2. Safety shoe,

3. Mask.

4. Gloves – Cotton knitted

5. Ear Plug

6. Safety belt

7. Goggles

TOOLS:

1. Box spanner set.

2. Ring spanner set.

Hazard Analysis:

Risks associated: Mitigating Measures

Dust emission Use Nose Make, Goggles & Ear Plug.

Tool Slip Use appropriate tools.

REPLACEMENT OF Thruster replacement:

1. Take the TLM in position.

2. Take LOTO Permit for truck loader.

3. Ensure to usage of PPE and dust mask where ever required.

4. Remove the thruster.



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01	Rev. No: 02	Effective Date:17.10.2017		SOP/MEC/052			
Issued By: M.R			Approved By: HOD -Mechanical				
SOP Thruster replacement							

- 5. Fix new thruster.
- 7. Clear the line clearance and take trial run.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below

JOB SAFETY ANALYSIS : (JSA)

Job Safety Analysis	Job: Replacement of wire rope	Date: 01/09/2014	Analysis by: Section Engineer	Reviewed by: Section Head		
Title of employee doing job:	Supervisor: Sr. Engr.	Department: Mechanical	Section: Plant	Approved by: HOD Mechanical		
Req'd/recommended PPE: Safety helmet, Safety shoe, & Hand gloves.						
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action		
Removing and fixing of thruster	Hit injury	Using the proper tools	Falling of thruster	Ensure the proper tools for holding thruster.		