

DALMIA CEMENT (B) LIMITED -Ariyalur

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01/11/2019 SOP/MEC/84

Issued By: Approved By: HOD Mechanical

SOP-JSA for Air blaster maintenance

Scope: Air blaster usage and Maintenance

Responsibility: Maintenance Technician

Accountability: Mechanical-Section Engineer

PPE:

- 1. Safety helmet,
- 2. Safety shoe,
- 3. Face Mask,
- 4. Safety belt.

TOOLS:

1. Required Tools

Hazard Analysis:

<u>Risks associated</u>: <u>Mitigation Method</u>

Inherent air in the line Disconnect the air line & Empty out the blaster

Procedure:

- 1. LOTO from Mechanical/Instrumentation for air supply & solenoid valve power supply.
- 2. By manual operation, operating the blaster and making sure of empting of cylinder.
- 3. Blaster maintenance to be carried out.
- 4. Dismantle the blaster components.
- 5. Check the Seals of the piston.
- 6. Check the piston for scoring, if it so replace the same.
- 7. Check Pressure relief valve, cleaning & Set point.
- 8. Clearing area and returning LOTO
- 9. Opening the air line valve and Taking trial run.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

1. JSA is enclosed below.



DALMIA CEMENT (B) LIMITED -Ariyalur

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01/11/2019 SOP/MEC/84

Issued By: Approved By: HOD Mechanical

SOP-JSA for Air blaster maintenance

Job Safety Analysis	Job: Maint. of Air Blaster	Date: 01/09/2014	Analysis by: Section Engineer	Reviewed by: Section Head	
Title of employee doing job:	Supervisor: Section Engineer	Department: Mechanical	Section: Mechanical	Approved by: HODMechanical	
Req'd /recommended PPE	: Insulated Tools, Safety	shoes			
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action	
Inherent air in the blaster	Air Blaster can function during maintenance.	It should be empty out.	Leakage in air line	Disconnect the Air line.	
Height work	Fall	Use Double lanyard Full body Safety harness.	May fail	Check before use, Wear properly.	

SL	Activity			Isolation Matrix for Preheater									
No				Isolation Type									
			EI	Electrical Energy					Other Energy				
5	Air Blaster Maintenance	Name and Tag for the	Res Sole	ate the pective enoid						Isolate the Air Valve		Di- presurise & Disconnect the Air	
		Equipment	Val	⁄e						varve		supply pipe.	