# **Dalmia** BHARAT CEMENT

### DALMIA CEMENT (B) LIMITED - Dalmiapuram



### **MECHANICAL SOP**

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MEC/36

Issued By: S & P Approved By: Head - Mech

REPLACEMENT OF FLUID COUPLING

**Scope:** To replace the fluid coupling

**Responsibility:** Engineer/SH

#### PPE:

1. Safety helmet

- 2. Safety shoe
- 3. Safety goggles
- 4. Gloves

#### **TOOLS:**

- 1 Spanner set
- 2 Sling
- 3 Hand gloves
- 4 Oil can

### **Hazard Analysis:**

Risks associated: Mitigating Measures

Fall of Coupling Use correct methods to remove

Fall of tools, Carry the tools in tool bags

# Procedure:-

- a. Take LOTO permit
- b. The LOTO Permit should be with the person who is working in the site
- c. Use PPE'S while working.
- d. Open the coupling guard.
- e. Provide the required packing support to coupling.
- f. Tie the coupling with Sling.
- g. Open the Multidisc assembly bolts.
- h. Take out the multidisc along with bushes.
- i. Open the bolts of resilient disc.
- j. Take out the fluid coupling.



### **DALMIA CEMENT (B) LIMITED - Dalmiapuram**



### **MECHANICAL SOP**

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MEC/36

Issued By: S & P Approved By: Head - Mech

REPLACEMENT OF FLUID COUPLING

k. Lift the new coupling & fix it.

I. Fix the Resilient disc bolts.

- m. Fix the Multidisc along with bolts & bushes.
- n. Tighten bolts of resilient disc & Multidisc.
- o. Rotate coupling to ensure free movement.
- p.Open the oil filling plug (any one of 2nos).
- q. Fill the oil with recommended grade
- r. Check the oil level
- s. Tighten the oil filling plug with "O" ring.
- t. Fix the coupling guard & ensure guard should not touch to shafts.
- u.Return the LOTO Permit

### **Emergency Shut- off:**

If body injury is there, First aid will be given and inform to the Safety department or Call Emergency number -222/9865125176/9865177444.

#### **Records/Annexure:**

Refer LOTO standards/permit & JSA is enclosed below.



## **DALMIA CEMENT (B) LIMITED - Dalmiapuram**



### **MECHANICAL SOP**

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MEC/36

Issued By: S & P Approved By: Head - Mech

REPLACEMENT OF FLUID COUPLING

# **JOB SAFETY ANALYSIS: (JSA)**

Job Safety Analysis	Job: Cooler water spray nozzle cleaning	Date: 01 – 06 - 2012	Analysis by SECTION ENGINEER	Reviewed by: SECTION HEAD
Title of employee doing job : Section engineer	Supervisor: Section Engineer	Department: Mechanical	Section:	Approved by: HOD

Reqd./recommended PPE's : Safety Helmet, Safet shoe, Hand Gloves, Safety goggles. Nose mask.

SI. No	Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What could go wrong	Corrective action
1	Removal of Drive guard	Major Injury	Use proper PPE	Slip/fall of guard	Allot trained workers
2	Removal of Coupling	Major Injury	Make proper arrangement & Use proper tools	Slip/fall	Allot trained workers.
3	Fixing of new coupling	Major Injury	Use proper tools	Slip/fall	Allot trained workers.

HEAD MECHANICAL

**HEAD TECHNICAL**