

DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/064

Issued By: M.R Approved By: HOD Mechanical

SOP Bucket Elevator Chain / Belt replacement

Scope: Bucket Elevator Maintenance & Inspection

Responsibility: Mechanical section Engineer Accountability: Mechanical section Manager

PPE:

Safety helmet.
 Safety shoe.

TOOLS:

1. Box spanner set

- 2. Ring spanner set
- 3. Chain Block
- 4. Wire rope slings
- 5. Manila / Nylon rope
- 6. "D" Shackle.
- 7. Local stop Key.

Hazard Analysis:

<u>Risks associated:</u> <u>Mitigating Measures</u>

Heavy Material : Use of Chain blocks & Ropes

Auxiliary Drive May start : 1) Keep the Auxiliary LPB is visibly locked & controlled.

: 2) Check and conform the Auxiliary derive LPBs (both top &

bottom) are working.

SOP for the Bucket elevator chain/belt replacement

- Take the Line clearance for the Main drive & Feeding gate concern with Process persons.
- Couple the clutch & Empty out the Bucket Elevator with the Auxiliary drive from local mode.
- Rotate the conveyor in Auxiliary mode, identify the damaged bucket and then stop the elevator after that get the line clearance.
- After LC taken, De-clutch the coupling.
- Take confined area work permit for sending the persons inside to work.

DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/064

Issued By: M.R Approved By: HOD Mechanical

SOP Bucket Elevator Chain / Belt replacement

• Inspect the Discharge chute without material if it is their remove the same without any material spillage.

- At the bottom side of the Elevator casing, remove all the bolts of the inspection door.
- Remove the dead stock material from the bottom side of the casing, if any. Feed the Material
 inside the circuit itself to reduce dust spillage.
- Check the oil level & qty inside the Gearbox if it is necessary fill/Drain the oil by manual pump without any spill.
- Remove the all buckets from the belt/chain.
- Remove & fix the belt/chain.
- Align the belt/chain in the pulley center.
- Remove the bolts from the bucket, take out the bucket.
- Re-fix the new bucket and tighten all the bolts, if possible with the required torque as mentioned by the OEM.
- Return the old buckets, belt, chains into stores.
- Return the Line clearance & work permit.
- Take trail for the elevator.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below



DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/064

Issued By: M.R Approved By: HOD Mechanical

SOP Bucket Elevator Chain / Belt replacement

Job Safety Analysis	Job: Bucket Elevator Maintenance / Inspection	Date: 01/09/2014	Analysis by: Section Engineer	Reviewed by: Section Head	
Title of employee doing job: Fitter	Supervisor: Section Engineer (Mech.)	Department: Mechanical	Section: Pyro, RVRM, CVRM, Packing Plant	Approved by: HOD Mechanical	

Req'd /recommended PPE:

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Opening inspection	Material May flush	Ensure the BOOT empty or keep the way to escape from the flushing Material	Material in Boot may release suddenly	Don't open all the bolts of the door, keep some bolts loosen at its place. Empty out without flushing
Open the inspection door	Loose material may fall from top of the Maintenance doo	Tap the casing before opening the inspection door to release loose material	Material may fall on the working personnel	Don't engage anybody at the top(Drive station)
Bucket may fall during handling for replacement.	Fingers trap	Use Suitable tools to handle (Chain Block, slings, etc)	Slings & chain tightening.	Take care of fingers at nip points



DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/064

Issued By: M.R Approved By: HOD Mechanical

SOP Bucket Elevator Chain / Belt replacement

Isolation Matrix:

S L N o	Activity		Tag / Name of the Equipment			
			Isolation Type			
			Electrical Energy	Other Energy		

1	SILO FEED BELT BUCKET ELEVATOR INTERNAL INSPECTION	Name and Tag for the Equipment	391MD1 SILO FEED BELT ELEVATOR DRIVE	391FN4 AIRSLIDE BLOWER		
2	REJECT BUCKET ELEVATOR INTERNAL INSPECTION	Name and Tag for the	361MD1 REJECT CHAIN ELEVATOR DRIVE	361BC1 -MILL REJECT BELT	331BC1-MILL FEED BELT	