

DALMIA CEMENT (B) LIMITED - Ariyalur

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 1.11.2019 SOP/MEC/017

Issued By: M.R Approved By: HOD Mechanical

KILN MIGRATION MEASUREMENTS

SCOPE: To measure the migration of Kiln

Responsibility: Engineer/SH

PPE:

- 1. Safety helmet,
- 2. Safety shoe,
- 3. Mask,
- 4. Safety goggles
- 5. Gloves
- 6. apron

TOOLS:

- 1. Piece of chalk
- 2. Measuring tape

Hazard Analysis:

<u>Risks associated:</u> <u>Mitigating Measures</u>

Hot shell Contact with body

Use of hand gloves/apron

Graphite chips may fall in to eye use of goggles

Procedure:

- 1. While running in the tyre NO: 1with chalk piece mark a small line which covers both shell as well as the tyre.
- 2. Use hand gloves while marking.
- 3. Use PPE'S while working.
- 4. Watch keenly till the same marking comes back to the partition.
- 5. Measure the gap between lines in shall and line in tyre which give the migration.
- 6. Check the same for all tyres.



DALMIA CEMENT (B) LIMITED - Ariyalur

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 1.11.2019 SOP/MEC/017

Issued By: M.R Approved By: HOD Mechanical

KILN MIGRATION MEASUREMENTS

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

JSA is enclosed below.

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: <u>KILN</u> <u>MIGRATION</u> <u>MEASUREMENTS</u>	Date: 20/08/2014	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job : Section engineer	Supervisor: Section Engineer	Department: Mech.	Section:	Approved by: HOD Mechanical

SI.No	Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What could go wrong	Corrective Action
1	Marking with chalk piece on tyre and retainer ring & measuring gap	Burn injury	Use of hand gloves	Kiln hot shell may touch to hand and cause burns	Toolbox talk and deploy trained employees
2	Marking with chalk piece on tyre and retainer ring & measuring gap	Eye injury	Use of safety goggles	Graphite block chips used for lubrication of supporting rollers may pierce in to eye health	Use safety goggles

LOTO: Not applicable.