DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - DPM



MECHANICAL SOP

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MEC/06

Issued By: S & P Approved By: Head - Mech

KILN SHELL MAINTENANCE

Scope:

This SOP is applicable for kiln shell maintenance safely.

Responsibility : Section Engineer - Mech

Accountability : Section head - Mech.

PPE:

- 1. Helmet,
- 2. Safety shoe,
- 3. Goggles
- 4. Gloves.
- 5. Nose mask
- 6. Full body harness.

Tools:

- 1. Spanner set
- 2. Hammer
- 3. Feeler gauge
- 4. Wire or nylon rope

Hazards:

Risks associated

- 1. Body injury
- 2. Leg injury
- 3. Hand injury

Mitigating Measures

- 1. Safe and tested tools and tackles
- 2. On job training

Isolation matrix:

SI:	Activity	Description	Electrical Energy	Other Energy
No	Activity	Description	Electrical Energy	Other Ellergy

DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - DPM



MECHANICAL SOP

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MEC/06

Issued By: S & P Approved By: Head – Mech

KILN SHELL MAINTENANCE

Take out DG ISOLATION OR PROVIDE STOPPERS IN BETWEEN Name and (461KL1) (461AD1) kiln shell Tag for the TYRE AND ROLLER- (During 1 Kiln main Kiln aux maintenance Equipmen rotation for checking of shell drive drive t ovality remove stopper & rotate with DG)

SOP FOR Maintenance of Kiln Shell

- 1. Take the energy isolation permit as per the above matrix
- 2. The line clearance paper should be with the person who is working in the site.
- 3. Take the work permit from the relevant department and allow the people to work.
- 4. Use ppe's while working.
- 5. Provide life line over the Kiln properly.
- 6. Provide staging for the respective areas for checking if required.
- 7. Check the condition of the shell for any ovality.
- 8. Check all shell joints welding for any cracks with ultrasonic testing.
- 9. Check shell condition at tyres position for any abnormality.

DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - DPM



MECHANICAL SOP

Issue No. 02	Rev. No: 01	Effe	ctive Date: 22.05.2015	SOP/MEC/06		
Issued By: S & P			Approved By: Head - Mech			
KILN SHELL MAINTENANCE						

- 10. After completion all the maintenance activities take out all unwanted and scrap material from the area.
- 11. Clear the line clearance

Emergency Shut- off:

- 1. In case of belt is moving, Emergency pull chord switch should be activated by the person.
- 2. If body injury is there, First aid will be given and inform to the Safety department or Call Emergency number 222/555/9865125176/9865177444.

Records/Annexure:

- 1. Refer Line clearance/permit in mech department.
- 2. JSA is enclosed below.

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job:	Date: 01/01/2013	Analysis by: SECTION ENGINEER	Reviewed by: SECTION HEAD
Title of employee doing job: Section Engineer	Supervisor: Section Head	Department: Mech	Section: PYRO	Approved by: G M. Mech.

Req'd/ recommended PPE: Safety helmet, Safety shoe, Gloves, Goggles, Gloves, Nose mask & Full body harness



DALMIA CEMENT (B) LIMITED - DPM



MECHANICAL SOP

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/MEC/06

Issued By: S & P Approved By: Head – Mech

KILN SHELL MAINTENANCE

Providing life line over the tyre	Body and hand injury	Use proper tools and tackles so that person will not slip	person may slip and fall	Ensure Use/working condition of TOOLS AND TACKLES.
Check for shell joints, thickness & condition	Body injury, hand injury & leg injury	Use life line & full body harness	Over the kiln shell person may slip & fall	Ensure Use of life line & full body harness
Checking of ovality	Body injury, hand injury & head injury	Ensure no one working inside kiln, cooler & in cyclone area while rotate by DG	Any other separate work may go inside or other area during rotation accidents may happen	Ensure no one is working inside kiln, cooler & in cyclone area while rotate by DG & get the clearance from respective dept before rotation
Checking of ovality	Body injury, hand injury & head injury	Use proper protection for head to avoid direct intact with kiln shell during rotation kiln for checking ovality reading in different location	Inaccessible as head, hand and body may hit or stuck to the shell gap during DG rotation	Ensure utmost care while checking the thrust roller.
Removal of the life line Body and hand injury		Use proper tools and tackles so that person will not slip	person may slip and fall	Ensure Use/working condition of TOOLS AND TACKLES.

HEAD MECHANICAL

HEAD TECHNICAL