DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL

Issue No. 02 Rev. No: 00 Effective Date: 01-11-2019 SOP/MEC/141

Issued By: M.R Approved By: HOD-Mechanical

SOP FOR ESP INSIDE CLEANING WORK

SCOPE: SOP FOR ESP INSIDE CLEANING WORK

Responsibility: Engineer/SH

PPE:

- 1. Safety helmet,
- 2. Safety shoe,
- 3. Mask,
- 4. Safety goggles
- 5. Gloves
- 6. Apron
- 7. Full body harness
- 8. Retractable lifeline

TOOLS:

- 1. Set of spanners
- 2.Rope ladder
- 3. Hammers

Hazard Analysis:

<u>Risks associated:</u> <u>Mitigating Measures</u>

Electrocution Follow Energy isolation permit

standards & procedures

Fine clinker dust may cause

eye irritation / injury Use safety goggles & dust mask

Fall of person/material Follow WAH procedures & standards

Breathing problem Follow CSE standards & procedures

Contact with hot surface Cool the ESP to atmosphere,

temperature before entering in, &

Follow HOT WORK standards &

procedures while cutting & welding job.



DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL

Issue No. 02	Rev. No: 00	Effective Date: 01-11-2019	SOP/M	1EC/141
7 ID 16D		4 ID 110D 14 I		

Issued By: M.R Approved By: HOD-Mechanical

SOP FOR ESP INSIDE CLEANING WORK

Procedure:

Please ensure the earthing connection for discharge the electrodes for all the fields is intact during the period of the maintenance.

- 1. Take Energy isolation permit.
- 2. Ask electrical dept. to discharge the ESP by giving earthing connection
- 3. Main key box should be opened by electrical dept.
- 4. Open the required chamber using the door key in the main key box.
- 5. Take confined space Permit
- 6. Take working at heights Permit
- 7. Check if any material inside the chambers,
- 8. Chamber material clean by hand blower
- 9. If Hopper materials found ,Rotary air lock Electrical isolation cleared and empty material by hammering the Hopper.
- 10. After completing the job. Ask electrical dept. to remove the earthing connection.
- 11. Check for any unwanted tools / welding rods inside.
- 12. Close all the doors ensure that there are no leakages.
- 13. Return the energy isolation
- 14. Start the field once and check for any abnormality in field.
- 15. If everything is under control give clearance to CCR to take ESP into circuit.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222



DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL

Issue No. 02 Rev. No: 00 Effective Date: 01-11-2019 SOP/MEC/141

Issued By: M.R Approved By: HOD-Mechanical

SOP FOR ESP INSIDE CLEANING WORK

Records/Annexure:

1. Refer OEM manuals.

2. JSA as enclosed below

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: ESP CLEANING WORK.	Date :28/09/2017	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job : Section engineer	Supervisor:	Department:	Section:	Approved by:
	Section Engineer	Mechanical	Pyro	HOD-Mechanical

Reqd./recommended PPE's : Safety Helmet, Safet shoe, Hand Gloves, Safety goggles. Nose mask.

SI. No	Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What could go wrong	Corrective action
1	Open the required chamber door	Electrocution	Follow the Electrical energy isolation and standards & procedures	Electrical burns	Allot trained workers Use PPE
3	Open and close the required chamber door opened and closed Hammering in Hopper	Hand injury Hand injury	Use safety PPE Use safety PPE	Hand Gloves Hand Gloves	Allot trained workers Use PPE Allot trained workers Use PPE
4	ESP Cleaning	Asphyxiation	Follow CSE standards & procedures	Breathing problem	O2 level check in every shift .Allot trained workers



DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL

Issue No. 02Rev. No: 00Effective Date: 01-11-2019SOP/MEC/141Issued By: M.RApproved By: HOD-Mechanical

SOP FOR ESP INSIDE CLEANING WORK

5	ESP Cleaning	Eye Irritation	Use Safety Goggles	Fine clinker dust may cause eye irritation /	Allot trained workers Use PPE
				injury	

SL No	Activity			Isolation Matrix For Cooler Isolation Type				
			Ele	Electrical Energy			Other Energy	
4	Cooler ESP	Name and Tag for the Equipment	ESP Fields	ESP fan	All RALs of the ESP	Rapping Drive	Discharge Earthing Connectio n for all the fields.	