# Dalmia BHARAT CEMENT

## **DALMIA CEMENT (B) LIMITED - Ariyalur**



#### **MECHANICAL SOP**

Issue No. 01 Rev. No: 02 Effective Date:17.10.2017 SOP/MEC/045

Issued By: M.R Approved By: HOD-Mechanical

### SOP FOR REPLACEMENT OF FLUID COUPLING (PEMBRIL MAKE

Scope: To replace the fluid coupling

**Responsibility:** Engineer/SH

#### PPE:

- 1. Safety helmet
- 2. Safety shoe
- 3. Safety goggles
- 4. Gloves

#### TOOLS:

- 1 Spanner set
- 2 Sling
- 3 Hand gloves
- 4 Oil can

#### **Hazard Analysis:**

<u>Risks associated:</u> <u>Mitigating Measures</u>

Fall of Coupling Use correct methods to remove

Fall of tools, Carry the tools in tool bags

## Procedure:-

- a. Take LOTO permit
- b. The LOTO Permit should be with the person who is working in the site
- c. Use PPE'S while working.
- d. Open the coupling guard.
- e. Provide the required packing support to coupling.
- f. Tie the coupling with Sling.
- g. Open the Multidisc assembly bolts.
- h. Take out the multidisc along with bushes.
- i. Open the bolts of resilient disc.
- j. Take out the fluid coupling.
- k. Lift the new coupling & fix it.



## **DALMIA CEMENT (B) LIMITED - Ariyalur**



#### **MECHANICAL SOP**

Issue No. 01 Rev. No: 02 Effective Date:17.10.2017 SOP/MEC/045
Issued By: M.R Approved By: HOD-Mechanical

### SOP FOR REPLACEMENT OF FLUID COUPLING (PEMBRIL MAKE

- l. Fix the Resilient disc bolts.
- m. Fix the Multidisc along with bolts & bushes.
- n. Tighten bolts of resilient disc & Multidisc.
- o. Rotate coupling to ensure free movement.
- p. Open the oil filling plug (any one of 2nos).
- q. Fill the oil with recommended grade
- r. Check the oil level
- s. Tighten the oil filling plug with "O" ring.
- t. Fix the coupling guard & ensure guard should not touch to shafts.
- u. Return the LOTO Permit.

#### **Emergency / Emergency Shut OFF:**

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

#### **Records/Annexure:**

Refer LOTO standards/permit & JSA is enclosed below.

## **JOB SAFETY ANALYSIS: (JSA)**

Job Safety Analysis	Job: Cooler water spray nozzle cleaning	Date: 01/09/2014	Analysis by: Section Engineer	Analysis by: Section Engineer	
Title of employee doing job : Section engineer	Supervisor: Section Engineer	Department: Mechanical	Section: All	Approved by: HOD-Mechanical	

Reqd./recommended PPE's: Safety Helmet, Safety shoe, Hand Gloves, Safety goggles. Nose mask.

SI. No	Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What could go wrong	Corrective action
1	Removal of Drive guard	Major Injury	Use proper PPE	Slip/fall of guard	Allot trained workers
2	Removal of Coupling	Major Injury	Make proper arrangement & Use proper tools	Slip/fall	Allot trained workers.
3	Fixing of new coupling	Major Injury	Use proper tools	Slip/fall	Allot trained workers.



## **DALMIA CEMENT (B) LIMITED - Ariyalur**



## **MECHANICAL SOP**

Issue No. 01Rev. No: 02Effective Date:17.10.2017SOP/MEC/045Issued By: M.RApproved By: HOD-Mechanical

## SOP FOR REPLACEMENT OF FLUID COUPLING (PEMBRIL MAKE

SL No	Activity		Tag / Name of the Equipment Isolation Type				
			Electrical Energy			Other Energy	
1	Fluid coupling replacement - SILO FEED BE	Name and Tag for the Equipment	BELT	391FN4 AIRSLIDE BLOWER			
2	Fluid coupling replacement - REJECT BE	Name and Tag for the Equipment	361MD1 REJECT CHAIN ELEVATOR DRIVE	361BC1 -MILL REJECT BELT	331BC1-MILL FEED BELT		+