# **Dalmia** BHARAT CEMENT

# DALMIA CEMENT (B) LIMITED - Ariyalur

## **MECHANICAL**

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/16

2

Issued By: Approved By: HOD-Mechanical

**SOP-JSA FOR STAND BY FAN ERECTION AND OPERATINGWORK** 

### STAND BY SEAL AIR FAN ERECTION AND OPERATION WORK

**Scope**: Motorizes gate erection and operating procedure

Responsibility: Maintenance Technician

**Accountability:** Mechanical-Section Engineer

PPE:

1. Safety helmet

2. Safety shoe

3. Nose Mask

4. Gloves

5. Goggles

#### TOOLS:

- 1. D Spanner Set.
- 2. Ring Spanner set.
- 3. Welding machine
- 4. Cutting machine
- 5. Grinding machine
- 6. Chain block 1ton
- 7. Belt sealing
- 8. Safety belt

#### **Hazard Analysis:**

Risks associated: Mitigating Measures

**Rotation of the Equipment** 

Electrical Hazard: Can be operated from remote

**Engagement of clutch:** Inter lock to be ensured

**Training needs:** 

- 1. Usage of tools and Nature of Hazards
- 2. Usage of PPE's

### **Procedure:**

1. Line clearance to be taken for the Seal air fan as per DCBL LOTO standard.

# DALMIA CEMENT (B) LIMITED - Ariyalur MECHANICAL Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/16 2 Issued By: Approved By: HOD-Mechanical SOP-JSA FOR STAND BY FAN ERECTION AND OPERATINGWORK

- 2. Erected the pipe line from existing line to stand by fan with help of chain block and fix
- 3. Give the power supply of isolation valve
- 4. Erected the fan as per specified location
- 5. Motor has to be fix
- 6. Motor and fan aliment has to be done
- 7. Connected the motor to fan
- 8. Electrical connection has to be done
- 9. After connecting trail has to be taken
- 10. Put the LOTO for new stand by seal air fan
- 11. Connected the pipe line with expansion joint stand by seal air fan
- 12. In between isolation valve has to fix in both fan pipe line.
- 13. Give power supply to isolation valve
- 14. Take trail open and close position
- 15. Give the logic modification for seal air fan trips stand by fan has to be run immediate.
- 16. Clear Permits & LOTO Clearance.
- 17. Give clearance to CCR
- 18. Whenever seal air fan trips stand by fan has to be run immediate with DCS.

#### **Emergency / Emergency Shut OFF:**

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

#### **Records/Annexure:**

- 1. Stand by fan erection work
- 2. JSA is enclosed below.



# DALMIA CEMENT (B) LIMITED - Ariyalur

# **MECHANICAL**

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/16

Issued By: Approved By: HOD-Mechanical

# **SOP-JSA FOR STAND BY FAN ERECTION AND OPERATINGWORK**

# **JOB SAFETY ANALYSIS : ( JSA)**

, = = = = = = = = = = = = = = = = = = =								
Job Safety Analysis	Job: Motorizes gate erection and operating procedure	Date: 1.11.2016	Analysis by; Section Engineer	Reviewed by: Section Head				
Title of employee doing job: Section Engineer	Supervisor: Section Head, Out Sourcing Supply Supervisor	Department: Mechanical	Section: Mills	Approved by: HOD				
eq'd/recommended PPE: Helmet, Shoe, Nose mask, Cotton Gloves, Leather gloves, Ear plug, Safety belt, Goggles, Shield								
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action				
Put on PP	ut on PP Exposure to fumes due to welding operation		Damaged goggl	Periodic replacement, Watch person should ensure				

#### Chain Block lifting Leg and hand injury Use proper tools and Chain block may Check the condition of tackles with certification slip from its lifting equipments. lifting position 1. Lifting Belts 2. Chain block Periodical replacement is recommended for belts and ropes. Periodical servicing required for Chain blocks. Check the condition of Chain Block fixing Body injury Use proper PPE (safety Safety belt failure PPE Periodical replacement is recommended for belts Use proper tools and Spanner slip Check the condition of flange bolt Hand injury loosening/tightening tackles with certification /Broken spanner Use proper cutting set Pipe line cutting Body injury Check the condition of Hose pipe with flash back arrester damage hose pipe. Periodical replacement is recommended

# **Dalmia**BHARAT CEMENT

# DALMIA CEMENT (B) LIMITED - Ariyalur

# **MECHANICAL**

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/16

Issued By: Approved By: HOD-Mechanical

# SOP-JSA FOR STAND BY FAN ERECTION AND OPERATINGWORK

Grinding the pipe and fix flange, positioning of valve	Eye and body injury	1.Use proper guard/locking and tested grinding machine 2.Ensure life of the grinding wheel	.Wheel may slip out from the machine 2.wheel broken	To cross check the tightness of wheel     check the expiry date of the grinding wheels.
positioning the expansion joint	Hand injury	Use proper tools and tackles with certification	Chain block may slip from its lifting position	Check the condition of lifting equipments.  1. Lifting Belts 2. Chain block  Periodical replacement is recommended for belts and ropes. Periodical servicing required for Chain blocks.
Welding operation	Hand and Eye injury	Use proper leather hand gloves and welding shield	Damage the welding shield glass and hand glove	Cross check the Periodical replacement of PPE

SL No	Activity		Tag / Name of the Equipment				
			Isolation Type				
			Electrical Energy			Other Energy	
01	Motorizes gate erection and operating procedure	Name and Tag for the Equipment	561 FN3 / seal air fan	Stan by seal air fan			