

DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



ELECTRICAL MANUAL

Issue No. 01 Rev. No: 01 Effective Date: 07.07.2017 ELEC/SOP/061

Issued By: M.R Approved By: HOD - ELECTRICAL

SOP for Electric Shock Treatment

Scope : All Electrical HT & LT Panels, Boards.

Responsibility: Engineer/Electricians

Accountability: Electrical Manager

PPE:

1. Nose mask

2. Goggles

3. Safety shoes

4. Safety helmet

5. Rubber hand gloves

Tools:

1. Hot Stick

2. Insulated tools

Hazards:

Risk Associated

Electrical Shock
Minor body injury

Electrocution (Fatal)

Mitigating Measures

Tested Electrical Rubber Hand Gloves Safety shoes, gloves, helmet, goggles

Re- fresher Training

Training needs:

1. Emergency preparedness

2. First aid including CPR training

3. Electrical safety training

Procedure:

1. BREAK THE ELECTRICAL CONTACT:

Free the Victim from electrical contact promptly, Switch of supply immediately if possible.

Otherwise use a Dry stick, dry rope, dry cloth or other nonconductor to separate the victim from the electrical contact. DONT USE BARE HANDS WITHOUT PROTECTION



DALMIA CEMENT (B) LIMITED - CEMENT PLANT **ARIYALUR ELECTRICAL MANUAL**



ELEC/SOP/061 Issue No. 01 **Rev. No: 01 Effective Date: 07.07.2017 Issued By: M.R**

Approved By: HOD - ELECTRICAL

SOP for Electric Shock Treatment

2. INSPECT THE VICTIM:

- Quickly feel the victim's mouth and throat and remove any foreign body (tobacco, false) teeth, etc...). If the mouth is tight shut, pay no more attention to it. Can be looked later. Begin artificial respiration immediately. ALSO SEND FOR DOCTOR .DELAY MAY RESULT DEATH.
- In case of prolonged artificial respiration, the victim can be laid on a Door or other flat surface so that his head and chest are six to eight inches lower than his feet. Flow of Blood to the Heart will be promoted and there will be better chance for recovery
- > The victim should not be moved from the place of artificial respiration until he is breathing normally on his own. He may than be moved but only in the lying position.

3. ARTIFICIAL RESPIRATION:

Position 1:



Place the victims face down with his arm folded one over the other and head resting on them.

Kneel down with one or both of your knees / near the victims head.

Place your hand on the on the victims back beyond the line of armpits, with

your fingers spread outwards and downwards and thumbs touching each other.

Position 2:



As you count one, two, three, move forward, keeping arm straight until they are nearly vertical, thus steadily pressing the victims back. This completes expiration.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR ELECTRICAL MANUAL



Issue No. 01 Rev. No: 01 Effective Date: 07.07.2017 ELEC/SOP/061

Issued By: M.R Approved By: HOD - ELECTRICAL

SOP for Electric Shock Treatment

Position 3:



As you proceed to count four, move backward releasing pressure and slide your hand down wards along the victims arm and grasp his upper arms just above the elbows. Continue to move backwards

Position 4:



As you move back counting five, six, seven raise and pull the victims arms towards you, until you feel tension in his shoulders. This expands his chest and results in respiration. As you count eight, lower the victim's arms, and move your hands up to the initial position.

Repeat above cycle 12 times a minute. When the victim starts breathing synchronize your steps with his breathing until he breaths strongly. Then stop

4. ARRANGE FOR STANDBY OPERATOR:

- In carrying out artificial respiration, it may be necessary to change the operator. This must be done without losing the rhythm of respiration.
- Continual artificial respiration for at least four hours. Breathing has returned even after eight hours in case of electric shock, but in such instances the victim will show some signs of recovery which will call for continued effort on the part of rescuers.
- After obtaining the Doctors advice on arrival, the victim can be shifted, and artificial respiration can also give simultaneously, if necessary.
- A brief return of natural respiration is not a certain indication for stopping the resuscitation permanently. The victim, after a temporary recovery of respiration, may stop breathing again. The victim must therefore be watched and if natural breathing stops, artificial respiration should be resumed immediately.



DALMIA CEMENT (B) LIMITED - CEMENT PLANT ARIYALUR ELECTRICAL MANUAL



Issue No. 01	Rev. No: 01	Effective Date: 07.07.2017		ELEC/SOP/061			
Issued By: M.R			Approved By: HOD - ELECTRICAL				
SOP for Electric Shock Treatment							

5. Never give an unconscious man anything to drink. It may choke him

Emergency / Emergency Shut OFF:

1. If any injury or electrical shock is there, give First aid and inform to the Safety department or Call Emergency number 3108/9865152222/9750963761.

Records/Annexure:

1. JSA as enclosed below.

JOB SAFETY ANALYSIS:(JSA)

Sequence of Basic	Potential	Recommended	What Could Go	Corrective Action			
Reqd./recommended PPE: Tested Electrical rubber hand gloves, Safety shoes, Safety helmet, Safety Goggle							
Title of employee doing job: Engineer / Electrician	Supervisor: Section Engineer	Department: Electrical	Section: Plant	Approved by: HOD			
Job Safety Analysis	Job: Trouble shooting in live panel	Date:	Analysis by: Section engineer	Reviewed by: Section head			

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Opening of live panel cover	Electric Shock Use Rubber Hand Gloves		Gloves validity may be expired	Inspect before use
	Panel flash over and Burned injury	Keep yourself beside the panel	Not fallow the procedure	Tool box talk/Proper Training
		Wear safety Goggles	Damaged goggles/non standard goggles/ Not wearing Goggle.	Periodic replacement/ Proper training