

DALMIA CEMENT (B) LIMITED - CEMENT PLANT ARIYALUR





Issue No: 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MECH/128 **Issued By: M.R**

Approved By: HOD - Mechanical SOP FOR SHAPING OPERATION

Scope:

To operate the shaping for machine the given job

Responsibly:

Engineer/SH

PPE:

Safety helmet Safety shoe Safety Goggles

Tools:

Spanner set Surface gauge Coolant Lighting **Cutting tools** Brush Spanner set

Hazard Analysis:

Risks associated:

- 1. Hot chips
- 2. Moving parts

Mitigating Measures

- 1. Goggles & gloves
- 2. Maintain distance from machine



Issue No: 01

Issued By: M.R

DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



MECHANICAL SOP

2 Effective Date: 17.10.2017 SOP/MECH/128

Approved By: HOD - Mechanical

SOP FOR SHAPING OPERATION

Procedure:

1. Clean and lubricate machine wherever necessary

Rev. No: 02

- 2. Positing the job in the vice and hold firmly
- 3. Set up the Ram stroke as per the requirement
- 4. Keep all bolts tightened before starting the operation
- 5. Maintain the distance away from the tool
- 6. Use appropriate speed as per the material of the job
- 7. Start the lubrication oil pump when the machine is running
- 8. Adjust tool post carefully while depth feeding
- 9. Do not touch the job with bare hands
- 10. Use coolant oil wherever necessary
- 11. While removing the job switch off the machine and keep the clutch in neutral position.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR MECHANICAL SOP



Issue No: 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MECH/128

Issued By: M.R Approved By: HOD - Mechanical

SOP FOR SHAPING OPERATION

Records/Annexure:

JSA as enclosed below.

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: Shaping operation	Date: 20.11.2014	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job: Section Engineer	Supervisor: Section Head	Department: Mechanical	Section: all area	Approved by: HOD Mechanical
Required/recommended PPE: Helmet, Shoe, Nose mask, Cotton Gloves, Ear plug, Safety belt, Goggles				
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Tools handling	Hands injury	Use Hand Gloves	Hands may injury	Use type of gloves accordingly.
Fall of small objects	Equipment damage.	Use proper Holding ropes other than lifting	Holding tool may failure	Check physically before use
Fall of object from base/ Hanging	Equipment damage	Check the base capability for handling the same.	Hooks welding may failure	Check before hanging / using.