

DALMIA CEMENT (B) LIMITED DPM



CONFINED SPACE RESCUE PLAN

Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/Mech/49

Issued By: S & P Approved By: Head- Mech

SOP FOR RESCUE PLAN IN COMBUSTIBLE VAPOURS IN CONFINED SPACE

SCOPE : Procedure for evacuating a person from Combustible vapours in Confined

Space areas.

Responsibility: Rescue Team.

PPE:

1. Fire proof suit

- 2. Safety helmet
- 3. Safety shoes
- 4. SCBA (Self Contained Breathing Apparatus)

Tools:

- 1. Fire Extinguishers
- 2. Tripod
- 3. Atmospheric Testing Equipment
- 4. Communication Equipment
- 5. 24 V Lighting Equipment with Transformer
- 6. LOTO Lock
- 7. Barriers & Signage boards

Hazards:

Risk Associated Mitigating Measures

Oxygen Deficiency Use SCBA for Air supply

Electrical fire Isolate the electrical source

Explosion severity Water spraying

Training needs:

- 1. Confined Space Entry Standards Training
- 2. Rescue Training
- 3. Fire fighting training
- 4. First aid training



DALMIA CEMENT (B) LIMITED DPM CONFINED SPACE RESCUE PLAN



Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/Mech/49

Issued By: S & P Approved By: Head- Mech

SOP FOR RESCUE PLAN IN COMBUSTIBLE VAPOURS IN CONFINED SPACE

Procedure:

- The Watch Person must be communicate to the Rescue team immediately after identifying a fire inside Confined Space through Mobile phone OR Public Address System OR Manual Call Point.
- 2. The Rescue team must assemble immediately at the Confined Space area with all the necessary equipments required for the safe rescue operations along with the Ambulance & Fire Engine.
- 3. Before entering into Confined Space, the rescue team personnel should ensure the area is safe to enter & LOTO (Lock out & Tag out) has to be done properly to minimize the fire enhancement.
- 4. Rescue personnel should use the SCBA (Self Contained Breathing Apparatus) in case atmosphere is still not safe to enter into the Confined Space for controlling fire & evacuating the victim.
- 5. The Tripod should be erected with all the safety measures in the Confined Space opening area for evacuating victim safely.
- 6. The area must be safeguarded with barriers & signage boards to avoid unwanted entry of people in the vicinity of Confined Space.
- 7. Rescue person should enter safely into Confined Space through ladder OR with retractable fall arrestor rope of Tripod.
- 8. If more rescue persons enter into the confined space, then they must ensure all the people are using SCBA for safe environment.
- 9. Water spraying must be used to put off the fire.
- 10. For Electrical appliances fire use DCP extinguishers to put off the fire.
- 11. CO2 extinguishers should not be used in Confined Space.



DALMIA CEMENT (B) LIMITED DPM CONFINED SPACE RESCUE PLAN



Issue No. 02 Rev. No: 01 Effective Date: 22.05.2015 SOP/Mech/49

Issued By: S & P Approved By: Head- Mech

SOP FOR RESCUE PLAN IN COMBUSTIBLE VAPOURS IN CONFINED SPACE

- 12. After putting off fire, Full body safety harness has to be fixed properly for the victim & the 'D' shackle of it has to be latched to the retractable fall arrestor rope.
- 13. Slowly the victim has to be pulled upwards by operating the hand roller of Tripod.
- 14. First Aid has to be given on the spot if required by Rescue personnel.
- 15. The victim must be shifted immediately to the hospital for further treatment.

Emergency:

- 1. In case of belt is moving, Emergency pull chord switch should be activated by the person.
- 2. If body injury is there, First aid will be given and inform to the Safety department or Call Emergency number 222/555/9865125176/9865177444.

Records/Annexure:

- 1. Refer Confined Space Entry Standards.
- 2. Refer Confined Space Entry Procedures.
- 3. Refer LOTO Standards
- 4. Refer LOTO Procedures

HEAD MECHANICAL

HEAD TECHNICAL