

## DALMIA CEMENT (B) LIMITED - ARIYALUR



## **MECHANICAL SOP**

Issue No. 01 Rev. No: 00 Effective Date: 30.09.2016 SOP/MEC/136

Issued By: M.R Approved By: HOD Mechanical

SOP FOR PRIMARY AND SECONDARY CRUHSER TOOTH SEGMENT HARD FACING

Scope: Crusher tooth segment hard facing job

Responsibility: Fitter/ Welder/ Supervisor

Accountability: Mechanical-Section Engineer / Section Head

### PPE:

1. Safety helmet.

- 2. Safety shoe.
- 3. Nose Mask.
- 4. Hand Gloves.
- 5. Goggles.
- 6. Leather apron.

#### **TOOLS:**

- 1. Welding shield
- 2. Welding machine
- 3. Chipping hammer
- 4. Wire Brush

#### **Hazard Analysis:**

Risks associated: Mitigating Measures

Slip of tools : Use appropriate tools

Electric shock : Use appropriate gloves & machine Earth system

### SOP FOR PRIMARY AND SECONDARY CRUHSER TOOTH SEGMENT HARD FACING

- 1. Use ppe's while working.
- 2. Take the worn out segments which has to be hard faced.



## DALMIA CEMENT (B) LIMITED - ARIYALUR



## **MECHANICAL SOP**

Issue No. 01 Rev. No: 00 Effective Date: 30.09.2016 SOP/MEC/136

Issued By: M.R Approved By: HOD Mechanical

SOP FOR PRIMARY AND SECONDARY CRUHSER TOOTH SEGMENT HARD FACING

- 3. Check the welding machine and holder condition for welding.
- 4. Check the height of the tooth's which has to be welded.
- 5. Cleaning of segment tooth's by wire brush.
- 6. Electrodes to be preheated by electrode ovens as per recommendations.
- 7. First Buffer layer welding to be done by buildup electrodes.
- 8. Buffer layer welding to be done up to 80mm height.
- 9. Second final layer welding to be done by Final coating electrodes.
- 10. Final layer welding to be done up to 85mm height (05mm).
- 11. Check the height of the welding layer with template.
- 12. Check for any welding cracks
- 13. Slags to be removed by chipping hammers.

### **Emergency / Emergency Shut OFF:**

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

### **Records/Annexure:**

1. JSA as enclosed below



# **DALMIA CEMENT (B) LIMITED - ARIYALUR**



# **MECHANICAL SOP**

Issue No. 01 Rev. No: 00 Effective Date: 30.09.2016 SOP/MEC/136

Issued By: M.R Approved By: HOD Mechanical

SOP FOR PRIMARY AND SECONDARY CRUHSER TOOTH SEGMENT HARD FACING

Job Safety Analysis	Job: Crusher tooth segment hard facing job	Date: 02/07/2016	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job: Crusher tooth segment hard facing job	Supervisor: Section Engineer	Department: Mechanical	Section: RMH Truck tippler	Approved by: HOD Mechanical

### Req'd/recommended PPE:

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Removing of chips	Body injury	Use appropriate tools	While removing slags, chipping hammer slip.	Use Correct type of tools and hammers.
Using the Welding machine	Hand injury (electric Shock)	Use proper Earth connection	While Welding the job ,secondary earth not connected properly	Check the earth connection before doing the welding