

DALMIA CEMENT (B) LIMITED - CEMENT PLANT

ARIYALUR

INSTRUMENTATION DEPARTMENT

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019		SOP/INST/34		
Issued By: M.R			Approved By:			
SOP FOR BAG COUNTING SYSTEM						

Scope/Purpose: This SOP is applicable for Bag counting system

Responsibility

: Instrument section - Engineer

Accountability

: Section In-Charge

PPE:

Tools:

- 1. Multi meter
- 2. Insulated screw driver
- 3. Insulated Pliers

Hazard Analysis:

Risks associated

Mitigating Measures

Electric shock

Usage of Insulated tools and Safety shoes

Training needs:

1. First aid procedures



DALMIA CEMENT (B) LIMITED - CEMENT PLANT

ARIYALUR

INSTRUMENTATION DEPARTMENT

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019		SOP/INST/34		
Issued By: M.R			Approved By:			
SOP FOR BAG COUNTING SYSTEM						

Procedure:

- 1. Check power supply
- 2. Check proper bag sensing
- 3. Check counter increment.

Emergency / Emergency Shut OFF:

_

Records/Annexure:

- 1. Daily check list
- 2. Sop for operating procedure

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: Maintenance of	Date: 20 – 09 - 2017	Analysis by:	Reviewed by:
	Bag counting system			



DALMIA CEMENT (B) LIMITED – CEMENT PLANT

ARIYALUR

INSTRUMENTATION DEPARTMENT

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019		SOP/INST/34		
Issued By: M.R			Approved By:			
SOP FOR BAG COUNTING SYSTEM						

Title of employee doing job: Instrument Mechanic	Supervisor: Section Engineer	Department: Instrumentation	Section: Instrument	Approved by:		
Req'd/recommended PPE: Insulated Tools, Safety shoes, Hand gloves						
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action		
Check the Power supply	Electrocution	Use insulated tools and multi meter	Multimeter probe insulation may be damaged	Check the multi meter probe condition before using for measurement		
Check proper bag sensing	may fall on leg No hazards	Inspect bag sensing from the long distance	Waste bags may hit on the leg	Inspect the Area before going for checking the sensitivity		
Check counter increment						