

DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL SOP

Issue No. 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MEC/73

Issued By: M.R Approved By: HOD Mechanical

ESP ELECTRODE / HAMMER REPLACEMENT

SCOPE: SOP FOR ESP ELECTRODE/HAMMER REPLACEMENT

Responsibility: Engineer/SH

PPE:

- 1. Safety helmet,
- 2. Safety shoe,
- 3. Mask,
- 4. Safety goggles
- 5. Gloves
- 6. Apron
- 7. Full body harness
- 8. Retractable lifeline
- 9. Rope ladder

TOOLS:

- 1. Hammer
- 2. Rope 1" dia 30 m length
- 3. Set of spanners
- 4. Chain blocks 2 tonn 2 no's
- 5. Wire slings 3m
- 6. Cutting set
- 7. Welding set
- 8. D shakles

Hazard Analysis:

Electrution

<u>Risks associated:</u> <u>Mitigating Measures</u>

Fine clinker dust may cause eye irritation / injury

Fall of person/material

Breathing problem

Contact with hot surface

follow LOTO standards & procedures use safety goggles & dust mask

follow WAH procedures & standards follow CSE standards & procedures

cool the ESP to atmosphere,

 $Temperature\ before\ entering\ in\ ,\ \&$

follow HOT WORK standards &

procedures while cutting & welding job.

DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL SOP

Issue No. 01	Rev. No: 02	Effective Date: 17.10.2017	SOP/MEC/73
--------------	--------------------	-----------------------------------	------------

Issued By: M.R Approved By: HOD Mechanical

ESP ELECTRODE / HAMMER REPLACEMENT

Procedure:

Please ensure the Farthing connection for discharge the electrodes for all the fields is intact during the period of the maintenance.

- 1. Take LOTO permit.
- 2. Ask electrical dept. to discharge the ESP by giving earthing connection
- 3. Main key box should be opened by electrical dept.
- 4. Open the required chamber using the door key in the main key box.
- 5. Check if any material is in hoppers, if any empty the material.
- 6. Take confined area clearance with safety officer.
- 7. Take working at heights clearance from the safety officer
- 8. Start replacing the hammer, taking minimum tools inside.
- 9. Remove the Hammer bolt & replace the new hammer.
- 10. After completing the job. Ask electrical dept. to remove the earthing connection.
- 11. Check for any unwanted tools / welding rods inside.
- 12. Close all the doors ensure that there are no leakages.
- 13. Return the line clearance to electrical dept. and safety officer.
- 14. Start the field once and check for any abnormality in field.
- 15. If everything is under control give clearance to CCR to take ESP into circuit.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

- 1. Refer OEM manuals.
- 2. JSA as enclosed below



DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL SOP

Issued By: M.R Approved By: HOD Mechanical

ESP ELECTRODE / HAMMER REPLACEMENT

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: ESP ELECTRODE / HAMMER REPLACEMENT.	Date : 01/09/2014	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job : Section engineer	Supervisor:	Department:	Section:	Approved by:
	Section Engineer	Mechanical	Pyro	HOD-Mechanical

Reqd./recommended PPE's : Safety Helmet, Safet shoe, Hand Gloves, Safety goggles. Nose mask.

SI. No	Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What could go wrong	Corrective action
1	Open the required chamber door.	Electrution	Follow the LOTO standards & procedures	Electrical burns	Allot trained workers Use PPE
2	Open the required chamber door.	Hand injury	Use safety PPE	Fine clinker dust may cause eye irritation / injury	Allot trained workers Use PPE
3	Inspection & replacement of hammer	asphyxiation	Follow CSE standards & procedures	Breathing problem	O2 level check in every shift .Allot trained workers
4	Hammer replacement	Burns	Follow HOT WORK standards & procedures.	Contact with hot surface	Allot trained workers



DALMIA CEMENT (B) LIMITED - Ariyalur



MECHANICAL SOP

Issue No. 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MEC/73

Issued By: M.R Approved By: HOD Mechanical

ESP ELECTRODE / HAMMER REPLACEMENT

SL No	Activity			Isolation Matrix For Cooler Isolation Type				
			Ele	Electrical Energy			Other Energy	
4	Cooler ESP	Name and Tag for the Equipment	IESP all the Fields	ESP fan	All RALs of the ESP	Raping Drive	Discharge Earthing Connetion for all the fields.	