DalmiaBHARAT CEMENT

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01 Rev. No: 02 Effective Date: 17.10.2017 SOP/MEC/029

Issued By: M.R Approved By: HOD-Mechanical.

SOP-JSA for Truck Loader Feed Drum Motor Replacement

Scope: Truck loader Feed Drum Motor replacement

Responsibility: Engineer

Accountability: Mechanical - Section Incharge

PPE:

1. Safety helmet,

- 2. Safety shoe,
- 3. Mask.
- 4. Gloves Cotton knitted
- 5. Ear Plug
- 6. Safety belt
- 7. Goggles

TOOLS:

- 1. Box spanner set.
- 2. Ring spanner set.
- 3. Chain pulley block.

Hazard Analysis:

<u>Risks associated:</u> <u>Mitigating Measures</u>

Dust emission Use Nose Make, Goggles & Ear Plug.

REPLACEMENT OF TRUCK LOADER FEED BELT DRUM MOTOR:

- **1.** Position the truck loader Inclined/feed/loading belt as required position.
- **2.** Take the line clearance for the truck loader.
- **3.** The line clearance paper should be with the person who is working in the site.
- 4. Use PPE'S while working.



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issue No. 01	Rev. No: 02	Effective Date: 17.10.2017		SOP/MEC/029
Issued By: M.R		Approved By: HOD-Mechanical.		

SOP-JSA for Truck Loader Feed Drum Motor Replacement

- **5.** Ensure proper uses of PPE'S tools and tackles.
- **6.** Remove the drum motor connections.
- **7.** Remove the locking arrangement of drum motor.
- **8.** Fix the chain block for removing of drum.
- **9.** Fix the new drum motor and align the drum motor with respect to Inclined/feed/loading belt.
- **10.** Fix the locking arrangement of drum motor.
- **11.** Realign and ensure the level in drum motor.
- **12.** Give the electrical connection and clear the line clearance.
- **13.** Take the trail run without load at local mode and take current load.

Emergency / Emergency Shut OFF:

1. If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL SOP

Issued By: M.R Approved By: HOD-Mechanical.

SOP-JSA for Truck Loader Feed Drum Motor Replacement

Job Safety Analysis:

Job Safety Analysis	Job: Replacement of Truck loader conv. drum motor	Date: 01/09/2014	Analysis by: Section Engineer.	Reviewed by: Section Head.
Title of employee doing job: Fitter	Supervisor: Section Engineer (Mech.)	Department: Mechanical	Section: Packing Plant	Approved by: HOD-Mechanical.

Req'd /recommended PPE:

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
Removing / Fixing the locking arrangement.	Hand injury.	Use appropriate tools.	Worker may use screw wrench spanner to remove the locking arrangement and result in injury.	Use the recommended D – Spanner or Ring spanner.
Make chain block arrangement.	Hand or Leg injury.	Select the appropriate chain block.	Failure of Chain Pulley block.	According to the weight of the drum motor chain block should be select.
1) Removing/Fixing the Drum motor from conveyor belt.	Hand or leg injury.	Use proper removing and lifting technique.	Drum motor may slip from the sling.	1) Job should be done by the trained person. 2) Chain block should be fixed in correct position.