Dalmia BHARAT CEMENT

DALMIA CEMENT (B) LIMITED - CHINNAKOMERLA



ELECTRICAL SMP

Issue No. 01 Rev. No: 01 Effective Date: 07.07.2017 SOP/ELE/030

Issued By: Approved By: HOD ELECTRICAL

Truck Loader Maintenance

Scope: Truck Loader Maintenance

Responsibility: Electrical section Technician / Section Engineer

Accountability: Electrical Section Engineer / Head

PPE:

1. Safety Hand Gloves (Suitable Electrical Insulated glove)

2. Safety Helmet,

- 3. Safety Shoe,
- 4. Nose mask.

TOOLS:

- 1. Screw Driver
- 2. Hand Blower
- 3. Fuse Remover/ Puller
- 4. Waste Cloth

Hazard Analysis:

Risk associated: Mitigation Measures

Effect of Shock Suitable Electrical Insulated glove

Effect of Eye Irritation Use of goggles

Dust inhalinataion Use of Nose mask

Procedure:

- 1. Take the truck loader down by pressing the hoist down push button.
- 2. Take LOTO for truck loader.
- 3. Open X3, X4, X5 & X7 JB blower it & check control cable tightness.
- 4. Open all the power JB & blower the JB.
- 5. Check for any loose connection in power JB.
- 6. Check Hoist & travel drive motor.
- 7. Check all the cable Festooning arrangement. If required replace the damaged wheel.
- 8. Check for the cable sag & tighten it if required.



DALMIA CEMENT (B) LIMITED - CHINNAKOMERLA



ELECTRICAL SMP

Issue No. 01	Rev. No: 01	Effe	ctive Date: 07.07.2017	SOP/ELE/030	
Issued By:			Approved By: HOD ELEC	TRICAL	
Truck Loader Maintenance					

- 9. Open the main control panel & blower it.
- 10. Check all the control & power cable tightness at the panel.
- 11. Open all the power contactor & clean with CRC.
- 12. Replace the power contactor kits if required.

Emergency Shut- off:

1. If electrical shock injury or body injury is there, give First aid and inform to the Safety department or Call Emergency number 3108/9865152222/9750963761.

Records/Annexure:

- 1. Refer Line clearance certificates.
- 2. JSA as enclosed below.



DALMIA CEMENT (B) LIMITED – CHINNAKOMERLA



ELECTRICAL SMP

Issue No. 01	Rev. No: 01	Effe	ctive Date: 07.07.2017	SOP/ELE/030	
Issued By:			Approved By: HOD ELECTRICAL		
Truck Loader Maintenance					

Job Safety Analysis	Job: Truck Loader Maintenance	Date:	Analysis by:	Reviewed by:	
Title of employee doing job: Technician	Supervisor: Sec.Engr	Department: Electrical	Section: Packing Plant	Approved by:	
Reqd./recommended PPE: Safety shoe, Helmet, Goggle, Nose mask					
Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action	
Isolation of feeder	Electrocution/Electrical fire	Use hand gloves Use Fire proof suit	Fail to use of PPE/suit	Educating importance of PPE through pep talk	
Cleaning of Motor body parts, Control JB's & Panel	Eye irritation,	Wear goggles	Damaged goggles / non standard goggles / Not wearing Goggle.	Periodic replacement / Proper training	
	Respiration problem	Wear Nose mask	Damaged nose mask/ Not wearing Nose mask	Periodic replacement / Proper training	
	Body injury	Wear safety helmet, safety shoes , hand gloves	Tools and material may fall on human body	Without PPE don't perform the job	
Measurement of IR / WR value of Motors	Body injury	Use proper tools	Nonstandard /damaged tools	Training for tools handling/ Periodic replacement	
		Wear safety helmet, safety shoes , hand gloves	Tools and material may fall on human body	Without PPE don't perform the job	
	Electrical shock	Use Tested Electrical Rubber Hand gloves	Damaged Gloves / Not checked before use	Periodic replacement/ To check for Damage before use	
		Use Calibrated meters. Good probes	Faulty meters, damaged probes	Meter shall be calibrated periodically. Check and ensure meter	



DALMIA CEMENT (B) LIMITED – CHINNAKOMERLA



ELECTRICAL SMP

Issue No. 01	Rev. No: 01	Effe	ctive Date: 07.07.2017	SOP/ELE/030	
Issued By:	Approved By: HOD ELECTRICAL			CTRICAL	
Truck Loader Maintenance					

				and probe condition before use.
Check the Contactor kit,	Eye irritation,	Wear goggles	Damaged goggles/non	Periodic replacement/
Open power contactor arc chute Clean arc chute and fixed and moving contact			standard goggles/ Not wearing Goggle.	Proper training
	Respiration problem	Wear Nose mask	Damaged nose mask/ Not wearing Nose mask	Periodic replacement / Proper training
	Body injury	Use proper tools	Nonstandard /damaged tools	Training for tools handling/ Periodic replacement
		Wear safety helmet, safety shoes , hand gloves	Tools and material may fall on human body	Without PPE don't perform the job